

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/01/2025

Submitted Date:

07/01/2025

Document Number:

717701507**FIELD INSPECTION FORM**Loc ID 336149 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	<a href="#">All Inspections</a>
Silver, Randy		randy.silver@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241905	WELL	PR	08/01/2019	GW	123-09696	FIRESTONE 'D' 1	PR

**General Comment:**

This is a follow up to prior inspection document #717701463. 1 CA was taken care of and 1 CA was not corrected.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: [Adequate](#)

Corrective Action:  Date:

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Other	#		
Comment:	<a href="#">Wellhead Assembly appears to be leaking and needs to be fixed for replaced. See attached FLIR Video</a>		
Corrective Action:	<a href="#">Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e</a>		Date: <a href="#">06/13/2025</a>

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	241905	Type:	WELL	API Number:	123-09696	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		PR							
Corrective Action:					Date:				
BradenHead									
Date of Last Brhd Test:		08/16/2024		Annual Brhd Completed?		Yes			
Last Brhd Test Results		Initial Surf Csg Pressure:		0		Fluid Type:			
		End Surf Csg Pressure:		0					
Comment:									
Corrective Action:					Date:				

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Optical Gas Imaging Survey**Survey Type: RoutineCurrent Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: \_\_\_\_\_ Long: \_\_\_\_\_

Wind: Calm Speed: 3 (mph) Direction From: SE Weather: Clear Temperature: 80 (F)Assisting Staff: \_\_\_\_\_ Camera #: 1☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
10:38	AM	10:40	AM	Wellhead(s)

Comment: It appears to be omitting emissions from the wellhead assembly.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**ECMC Comments**

Comment	User	Date
<p><b>ECMC Inspection Report Summary</b></p> <p>On Tuesday, July 1, 2025, at approximately 10:35 AM, Inspector Adam Burns conducted an on-site inspection to prior inspection document #717701463 at the following location:</p> <p>Well: Firestone 'D' 1 Operator: KP Kauffman Company Inc. API #05-123-09696 County: Weld</p> <p>During the inspection, the following possible compliance issues were identified: Mechanical Conditions: Wellhead Assembly appears to be leaking and needs to be fixed for replaced. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. CA date of 6/13/25 It appears to be omitting emissions from the wellhead assembly. Stained soil was removed. A follow-up inspection is scheduled to ensure that the compliance issues have been rectified to comply with ECMC rules. Please note that any corrective actions from previous inspections that have not been addressed remain applicable.</p>	burnsa	07/01/2025

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717701508	Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7124200">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7124200</a>
717701509	FLIR Video	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7124201">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7124201</a>