

# Inspection Photos

06/06/2025

**Operator:** QB ENERGY OPERATING LLC

#10844

**Location ID:** 334855

**Inspection Doc:** 719200013

Garfield County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334855



**Photo 1:** Photos taken from the central portion of the Location and provide an overview of the Location looking north and south, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334855



**Photo 2:** Photos taken from the central portion of the Location and provide an overview of the Location looking east and west, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334855



**Photo 4:** Photo example of undesirable plant species that have established on the southern portion of the Location. Russian knapweed and cheatgrass have established at the edges of the interim areas.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334855



**Photo 5:** An unused guy-line anchor was observed on the western portion of the site. Marking or removal is required.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334855



**Photo 6:** Debris located in the culvert and near the access road. Removal is required.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334855



**Photo 7:** Photos showing an example of light sediment tracking observed on the western portion of the Location. Gravel has not been applied to the entire pad. BMP's show signs of disrepair; maintenance is advised.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources