

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC SHAEFFER 12-14B (012) Pad

Location #: 334650



Photo # 9142 From entrance to location




Photo # 9143 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC SHAEFFER 12-14B (012) Pad

Location #: 334650



Photo # 9144 Location



Photo # 9145 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC SHAEFFER 12-14B (012) Pad

Location #: 334650



Photo # 9146 Location



Photo # 9147 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC SHAEFFER 12-14B (012) Pad

Location #: 334650



Jul 1, 2025 at 12:39:01 PM
CO



Jul 1, 2025 at 12:42:00 PM
CO

Photo # 9148 Location

Photo # 9149 Location



Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC SHAEFFER 12-14B (012) Pad

Location #: 334650



Photo # 2213 From inspection/audit 708906562 conducted on 05/21/2025 Unused flowline lacks lockout tagout (OOSLAT)



Photo # 9150 Unused flowline lacks tag/not in compliance with CECMC rules

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC SHAEFFER 12-14B (012) Pad

Location #: 334650



Photo # 9151 Unused flowline lacks tag/not in compliance with CECMC rules



Photo # 9152 Weeds in secondary containment

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC SHAEFFER 12-14B (012) Pad

Location #: 334650



Photo # 9153 Weeds in secondary containment