

## Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC PL35NW PAD

Location ID: 424424

Date: 07/1/2025



Photo # 9232 Entrance to location



Photo # 9262 Location



## Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC PL35NW PAD

Location ID: 424424

Date: 07/1/2025



Photo # 9234 Location



Photo # 9242 Location



## Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC PL35NW PAD

Location ID: 424424

Date: 07/1/2025



Photo # 9252 Location



Photo # 9261 Location

## Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC PL35NW PAD

Location ID: 424424

Date: 07/1/2025



Photo # 9272 Location



Photo # 9283 NE corner of location



## Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC PL35NW PAD

Location ID: 424424

Date: 07/1/2025



Photo # 9284 SE corner of location



Photo # 9285 SW corner of location

## Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC PL35NW PAD

Location ID: 424424

Date: 07/1/2025



Photo # 9286 NW corner of location



Photo # 9247 Hole in separator building/wildlife hazard/available for entry by wildlife



## Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC PL35NW PAD

Location ID: 424424

Date: 07/1/2025



Photo # 9256 Unused flowline does not comply with CECMC 600 & 1100 series rules



Photo # 9257 Unused flowline does not comply with CECMC 600 & 1100 series rules



## Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC PL35NW PAD

Location ID: 424424

Date: 07/1/2025



**Photo # 9259 Unused flowline does not comply with CECMC 600 & 1100 series rules**



**Photo # 9288 Loose barbed wire fencing/wildlife hazard**



## Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC PL35NW PAD

Location ID: 424424

Date: 07/1/2025



Photo # 9290 Loose barbed wire fencing/wildlife hazard



Photo # 9292 Loose barbed wire fencing/wildlife hazard



## Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC PL35NW PAD

Location ID: 424424

Date: 07/1/2025



Photo # 9294 Loose barbed wire fencing/wildlife hazard



Photo # 9299 Loose barbed wire fencing/wildlife hazard



## Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC PL35NW PAD

Location ID: 424424

Date: 07/1/2025




Photo # 9254 Sign on dehydrator building is inaccurate



Photo # 9271 Label on methanol tank has incorrect operator name