

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/12/2025

Submitted Date:

07/03/2025

Document Number:

718800441

**FIELD INSPECTION FORM**Loc ID 330386 Inspector Name: Mitchem, Katelyn On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

6 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                                     | Comment |
|--------------|-------|---|---------|
| ,            |       | rbucogccinspectionreports@c<br>hevron.com |         |

**Inspected Facilities:**

| Facility ID | Type     | Status | Status Date | Well Class | API Num   | Facility Name               | Insp Status |
|-------------|----------|--------|-------------|------------|-----------|-----------------------------|-------------|
| 251204      | WELL     | PA     | 06/18/2019  | GW         | 123-19007 | HSR-FOSTER 4-35             | RI          |
| 330386      | LOCATION | CL     |             |            | -         | HSR-FOSTER-63N65W<br>35NWNW | RI          |

**General Comment:**

This is a final reclamation inspection at PA Well API# 123-19007 and its associated tank battery. The well was plugged and abandoned on 06/18/2019.

Location

Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good: ☐

Spills:

| Type   | Area | Volume |  |  |
|--|------|--------|--|--|
| In Containment: No                                     |      |        |  |  |
| Comment:   |      |        |  |  |
| <input type="checkbox"/> Multiple Spills and Releases? |      |        |  |  |

Equipment:

| Type:              | # |   | corrective date |
|--------------------|---|---|-----------------|
| Comment:           |   | No visual evidence of oil and gas equipment at the location. Refer to the attached inspection photos. |                 |
| Corrective Action: |   | Date:   |                 |

Venting:

|                    |  |       |
|--------------------|--|-------|
| Yes/No             |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

Flaring:

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |

| Inspected Facilities   |        |       |          |             |           |         |    |               |    |
|--|--------|-------|----------|-------------|-----------|---------|----|---------------|----|
| Facility ID:   | 251204 | Type: | WELL     | API Number: | 123-19007 | Status: | PA | Insp. Status: | RI |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |       |          |             |           |         |    |               |    |
| Facility ID:   | 330386 | Type: | LOCATION | API Number: | -         | Status: | CL | Insp. Status: | RI |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |       |          |             |           |         |    |               |    |

| Environmental  |                   |                               |       |
|--|-------------------|-------------------------------|-------|
| <b>Spills/Releases:</b>  |                   |                               |       |
| Type of Spill: _____   |                   | Estimated Spill Volume: _____ |       |
| Comment: <div>ECMC confirms that all remediation projects are approved and closed.</div> |                   |                               |       |
| Corrective Action: _____   |                   | Date: _____                   |       |
| Reportable: _____  | GPS: Lat _____    | Long _____                    |       |
| Proximity to Surface Water: _____  |                   | Depth to Ground Water: _____  |       |
| <b>Water Well Complaint:</b>   |                   |                               |       |
|  |                   | Lat                           | Long  |
| DWR Receipt Num: _____   | Owner Name: _____ | GPS :                         | _____ |
| <b>Field Parameters:</b>   |                   |                               |       |
|  |                   |                               |       |
| Sample Location: _____   |                   | Comment: _____                |       |

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

- 1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_
- 1003c. Compacted areas have been cross ripped? \_\_\_\_\_
- 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_
- Cuttings management: \_\_\_\_\_
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_
- Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged Pass Pit mouse/rat holes, cellars backfilled Pass

Debris removed Pass No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded Pass Contoured Pass Culverts removed Pass

Gravel removed Pass

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% **Fail** Cropland: perennial forage \_\_\_\_\_

Weeds present **Fail** Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: **This location does not meet reclamation regulations as vegetation establishment does not meet Rule 1004 standards at the tank battery location and at the entrance to the access road, and weedy annual vegetation was observed across those locations.**

**The well location appears to meet final reclamation regulations and standards. Unable to find evidence of oil and gas activities and/or disturbances.**

Inspector Name: Mitchem, Katelyn

|   |  |  |                          |                     |                          |         |       |  |
|---|--|--|--------------------------|---------------------|--------------------------|---------|-------|--|
| Corrective Action:  | Comply with Rule 1004 to perform additional reclamation activities at the tank battery location and access road and perform weed management. |  |                          |                     |                          | Date    |       |  |
| Overall Final Reclamation                                   | Fail   | Well Release on Active Location  | <input type="checkbox"/> | Multi-Well Location | <input type="checkbox"/> |         |       |  |
| <b>Storm Water:</b>   |  |  |                          |                     |                          |         |       |  |
| Loc Erosion BMPs  | BMP Maintenance  | Lease Road Erosion BMPs  | Lease BMP Maintenance    | Chemical BMPs       | Chemical BMP Maintenance | Comment |       |  |
|   |  |  |                          |                     |                          |         |       |  |
| Comment:  |  | At the time of this inspection, no stormwater erosion issues were observed at the location or along the access road. |                          |                     |                          |         |       |  |
| Corrective Action:  |  |  |                          |                     |                          |         | Date: |  |
| Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT |  |  |                          |                     |                          |         |       |  |

### Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 718800442    | Inspection Photos | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7127940">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7127940</a> |