

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Currier 26-15 PAD

Location ID: 334528

Date: 07/1/2025



Photo # 9307 Entrance to location



Photo # 9334 Location

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Currier 26-15 PAD

Location ID: 334528

Date: 07/1/2025



Photo # 9308 Location



Photo # 9309 Location

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Currier 26-15 PAD

Location ID: 334528

Date: 07/1/2025



Photo # 9323 Location



Photo # 9332 Location

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Carrier 26-15 PAD

Location ID: 334528

Date: 07/1/2025



Photo # 9402 Location - Weeds/undesirable plant species surrounding production equipment constitutes a fire hazard



Photo # 9404 NW corner of location

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Currier 26-15 PAD

Location ID: 334528

Date: 07/1/2025



Photo # 9405 NE corner of location



Photo # 9406 SE corner of location

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Carrier 26-15 PAD

Location ID: 334528

Date: 07/1/2025



Photo # 9407 SW corner of location



Photo # 9343 Multiple holes in secondary containment liner/liner needs maintenance

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Currier 26-15 PAD

Location ID: 334528

Date: 07/1/2025



Photo # 9345 Multiple holes in secondary containment liner/liner needs maintenance



Photo # 9346 Multiple holes in secondary containment liner/liner needs maintenance

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Currier 26-15 PAD

Location ID: 334528

Date: 07/1/2025



Photo # 9347 Multiple holes in secondary containment liner/liner needs maintenance



Photo # 9348 Multiple holes in secondary containment liner/liner needs maintenance

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Currier 26-15 PAD

Location ID: 334528

Date: 07/1/2025



Photo # 9349 Multiple holes in secondary containment liner/liner needs maintenance



Photo # 9350 Multiple holes in secondary containment liner/liner needs maintenance

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Currier 26-15 PAD

Location ID: 334528

Date: 07/1/2025



Photo # 9353 Multiple holes in secondary containment liner/liner needs maintenance



Photo # 9354 Multiple holes in secondary containment liner/liner needs maintenance

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Currier 26-15 PAD

Location ID: 334528

Date: 07/1/2025



Photo # 9355 Multiple holes in secondary containment liner/liner needs maintenance



Photo # 9356 Multiple holes in secondary containment liner/liner needs maintenance

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Currier 26-15 PAD

Location ID: 334528

Date: 07/1/2025



Photo # 9357 Multiple holes in secondary containment liner/liner needs maintenance



Photo # 9366 Multiple holes in secondary containment liner/liner needs maintenance

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Currier 26-15 PAD

Location ID: 334528

Date: 07/1/2025



Photo # 9367 Multiple holes in secondary containment liner/liner needs maintenance



Photo # 9368 Multiple holes in secondary containment liner/liner needs maintenance

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Carrier 26-15 PAD

Location ID: 334528

Date: 07/1/2025



Photo # 9371 Unused flowline does not comply with CECMC 600 & 1100 series rules



Photo # 9372 Unused flowline does not comply with CECMC 600 & 1100 series rules

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Carrier 26-15 PAD

Location ID: 334528

Date: 07/1/2025



Photo # 9373 Multiple unused flowlines do not comply with CECMC 600 & 1100 series rules



Photo # 9374 Multiple unused flowlines do not comply with CECMC 600 & 1100 series rules

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Carrier 26-15 PAD

Location ID: 334528

Date: 07/1/2025



Photo # 9375 Multiple unused flowlines do not comply with CECMC 600 & 1100 series rules



Photo # 9376 Multiple unused flowlines do not comply with CECMC 600 & 1100 series rules

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Carrier 26-15 PAD

Location ID: 334528

Date: 07/1/2025



Photo # 9377 Multiple holes in separator buildings open to wildlife/ available for entry by wildlife



Photo # 9378 Multiple holes in separator buildings open to wildlife/ available for entry by wildlife

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Carrier 26-15 PAD

Location ID: 334528

Date: 07/1/2025



Photo # 9379 Hole in separator building/wildlife hazard/available for entry by wildlife



Photo # 9380 Hole in separator building/wildlife hazard/available for entry by wildlife

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Carrier 26-15 PAD

Location ID: 334528

Date: 07/1/2025



Jul 1, 2025 at 2:52:44 PM
+39.241824,-107.846293 ±4.16m

Photo # 9381 PRV vent line does not comply with CECMC pressure safety device rules



Jul 1, 2025 at 2:56:34 PM
+39.241612,-107.846108 ±3.38m

Photo # 9384 Weeds/undesirable plant species surrounding production equipment constitutes a fire hazard

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Carrier 26-15 PAD

Location ID: 334528

Date: 07/1/2025



Photo # 9387 Weeds/undesirable plant species surrounding production equipment constitutes a fire hazard



Photo # 9389 Weeds/undesirable plant species surrounding production equipment constitutes a fire hazard

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Currier 26-15 PAD

Location ID: 334528

Date: 07/1/2025



Photo # 9392 Weeds/undesirable plant species surrounding production equipment constitutes a fire hazard



Photo # 9393 Weeds/undesirable plant species surrounding production equipment constitutes a fire hazard

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Currier 26-15 PAD

Location ID: 334528

Date: 07/1/2025



Photo # 9395 Weeds/undesirable plant species surrounding production equipment constitutes a fire hazard



Photo # 9396 Weeds/undesirable plant species surrounding production equipment constitutes a fire hazard

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Carrier 26-15 PAD

Location ID: 334528

Date: 07/1/2025



Photo # 9398 Weeds/undesirable plant species surrounding production equipment constitutes a fire hazard



Photo # 9399 Weeds/undesirable plant species surrounding production equipment constitutes a fire hazard

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Currier 26-15 PAD

Location ID: 334528

Date: 07/1/2025



Photo # 9400 Weeds/undesirable plant species surrounding production equipment constitutes a fire hazard



Photo # 9401 Weeds/undesirable plant species surrounding production equipment constitutes a fire hazard