

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/01/2025

Submitted Date:

07/01/2025

Document Number:

716301186**FIELD INSPECTION FORM**Loc ID 333417 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1875 LAWRENCE ST STE 1150City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Evergreen	719-846-7898	cogcc.evergreen@enrllc.com	<a href="#">All Inspections</a>
D DYKE, TRACY	719-846-7898	tracy.dyke@enrllc.com	<a href="#">Insp. w/ca's</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287035	WELL	SI	03/01/2025	CBM	071-09006	ULIBARRI 32-6 R	SI

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	PHOTO 5: DEAD WEEDS AROUND LOCATION ARE A FIRE HAZARD.		
Corrective Action:	CUT AND REMOVE DEAD WEEDS PER RULE 606.		Date: <u>07/12/2025</u>
Type	OTHER		
Comment:	PHOTO 6: THERE IS AN AREA OF IMPACED SOILS AROUND THE PRIME MOVER ENGINE SKID.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,.(2).D		Date: <u>07/12/2025</u>
Type	WEEDS		
Comment:	PHOTO 4: WEEDS OVERGROWN AROUND LOCATION.		
Corrective Action:	WEEDS INSIDE ANCHORS NEED TO BE MAINTAINED PER RULE 606.		Date: <u>07/12/2025</u>

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR. METER WILL NEED CALIBRATED BEFORE THE END OF THIS MONTH TO REMAIN IN COMPLIANCE.		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	IS ACCESSABLE		

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 7		
Comment:	PHOTO 8: ANCHOR MARKER IS DOWN ON THE NORTH EAST ANCHOR FROM WELLHEAD.		
Corrective Action:	Install proper guy line markers per Rule 1003.a. CA DATE 7-2-2025 DUE TO GROWNING SEASON FARM HAND WAS CUTTING AT TIME OF INSPECTION.		Date: 07/02/2025

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	287035	Type:	WELL	API Number:	071-09006	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: WELL LAST PRODUCED JULY 2024.									
Corrective Action: _____ Date: _____									
BradenHead									
Date of Last Brhd Test: 11/19/2011 Annual Brhd Completed? _____									
Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____									
End Surf Csg Pressure: 0									
Comment: FORM 4 ON FILE									
Corrective Action: _____ Date: _____									
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: PHOTO 7: OILY WASTE IN PRIME MOVER ENGINE SKID.

Corrective Action: DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. 24 HOURS TO REMOVE OILY WASTE

Date: 07/12/2025

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404264350	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7124317">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7124317</a>
716301187	INSP. PHOTOS	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7124310">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7124310</a>