

## LOWE 1-2 R

### Photo Log

**Inspection Comment:** Animal burrows were visible in multiple areas of the shared production tank and produced water vessel containment berm, and at the separator containment berm.

**Corrective Action Requested:** Repair or install berms or other secondary containment devices per Rule 603.o

**Description of Compliance:** Berms were repaired and brought into compliance.

