


TEP KP 11-16 Location ID: 335557



Location



Location

TEP
KP 11-16
Location ID: 335557



Location



Location

TEP
KP 11-16
Location ID: 335557



Location



Cut slope lacks stabilization

TEP
KP 11-16
Location ID: 335557



Cut slope lacks stabilization



Sediment from cut slope erosion