

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/08/2025

Submitted Date:

07/09/2025

Document Number:

707801693

FIELD INSPECTION FORMLoc ID 335557 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

18 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
300989	WELL	PR	01/01/2021	GW	045-18064	JOLLEY KP 11-16	PR
301002	WELL	PR	09/01/2013	GW	045-18068	JOLLEY KP 321-16	PR
301005	WELL	PR	03/24/2013	GW	045-18069	Jolley KP 14-9	PR
301006	WELL	PR	02/01/2020	GW	045-18070	JOLLEY KP 314-9	PR
301007	WELL	PR	03/24/2013	GW	045-18071	Jolley KP 414-9	PR
301008	WELL	PR	03/04/2016	GW	045-18072	Jolley KP 514-9	PR
426794	WELL	PR	05/30/2013	GW	045-21199	Jolley KP 444-8	PR
426798	WELL	PR	05/31/2013	GW	045-21200	Jolley KP 434-9	PR
426801	WELL	PR	05/31/2013	GW	045-21201	Jolley KP 24-9	PR
426808	WELL	PR	05/30/2013	GW	045-21202	Jolley KP 324-9	PR
426834	WELL	PR	03/22/2013	GW	045-21208	Jolley KP 424-9	PR
426840	WELL	PR	05/01/2013	GW	045-21209	Jolley KP 344-8	PR

General Comment:

CECMC Inspection Report Summary

On Tuesday 7/8/2025, I, Inspector Scott Ramsey, conducted a follow up inspection/audit at TEP KP 11-16, at Location # 335557 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad. No evidence of a tracking pad on location.

C/A's from previous inspection document # 708303836 has been addressed.

During this inspection the following compliance issues were observed:

1. Cut slope lacks stabilization

Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

LocationOverall Good: ☐**Signs/Marker:**

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:Comment: [911/970-285-9377](tel:9119702859377)

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Bradenhead	# 12		corrective date
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 14		
Comment:			
Corrective Action:		Date:	

Type: Bird Protectors	# 17	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 12	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment:	Chemical tank in plastic containment	
Corrective Action:		Date:
Type: Gas Meter Run	# 12	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	6	300 BBLS	HEATED STEEL AST		,
Comment:	3 tanks are not heated				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	6	300 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID:	300989	Type:	WELL	API Number: 045-18064 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	301002	Type:	WELL	API Number: 045-18068 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	301005	Type:	WELL	API Number: 045-18069 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	301006	Type:	WELL	API Number: 045-18070 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	301007	Type:	WELL	API Number: 045-18071 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	301008	Type:	WELL	API Number: 045-18072 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	426794	Type:	WELL	API Number: 045-21199 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	426798	Type:	WELL	API Number: 045-21200 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Producing Well			
Comment:	Producing		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	426801	Type:	WELL
API Number:	045-21201	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	426808	Type:	WELL
API Number:	045-21202	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	426834	Type:	WELL
API Number:	045-21208	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	426840	Type:	WELL
API Number:	045-21209	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
Berms						
Gravel						
		Culverts				
		Ditches				

Comment: 1. Cut slope lacks stabilization
The cut slope on the location is not stabilized. Portions of the slope appear to be sloughing off, as the cut is almost vertical. The top of the slope appears to be undercutting. Sediment from the slope was observed accumulating at the slope base.

Corrective Action: Install, maintain or repair required BMPs

Date: 08/20/2025

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707801699	Photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7134839