

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CSF 33B-07-07-91 Pad

Location # 335051



Photo # 289 From entrance to location



Photo # 290 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CSF 33B-07-07-91 Pad

Location # 335051



Photo # 291 Location



Photo # 292 Location



## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CSF 33B-07-07-91 Pad

Location # 335051



**Photo # 6182 From inspection/audit 708906074 conducted on 03/20/2025 PRV vent line on separator does not comply with CECMC pressure safety device rules**



**Photo # 293 PRV vent line on separator does not comply with CECMC pressure safety device rules**

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CSF 33B-07-07-91 Pad

Location # 335051



**Photo # 6183 From inspection/audit 708906074 conducted on 03/20/2025 PRV vent line on separator does not comply with CECMC pressure safety device rules**



**Photo # 294 PRV vent line on separator does not comply with CECMC pressure safety device rules**


## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CSF 33B-07-07-91 Pad

Location # 335051



**Photo # 6184 From inspection/audit 708906074 conducted on 03/20/2025 Bird protection on separator insufficient /burner stack available for entry by wildlife/wildlife hazard**



**Photo # 295 Bird protection on separator insufficient /burner stack available for entry by wildlife/wildlife hazard**



## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CSF 33B-07-07-91 Pad

Location # 335051



Photo # 6185 From inspection/audit 708906074 conducted on 03/20/2025 Wellhead sign lacks required information



Photo # 296 Wellhead sign lacks required information