

Final Reclamation and Stormwater Inspection

July 2, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 422767

Well Name: MILLER X #31-03

Inspection Document #: 718600740

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos
Location Name: MILLER X #31-03
Location ID: 422767



Photo 1. Picture taken at the entrance of the access road. The access road remains bare soil. The soil on the access road is more compacted than surrounding soil.



Photo 2. Looking north down the access road to the midpoint. It appears that reclamation such as drill seeding may have been conducted on the access road. Vegetation on the access road is primarily undesirable weed kochia and list C noxious weed cheatgrass. Germination of desirable plant species was not observed at the time of inspection.



Inspection Photos
Location Name: MILLER X #31-03
Location ID: 422767



Photo 3. Looking north across the wellbore. No oil and gas equipment remains. Vegetation around the wellbore is primarily undesirable weed kochia and list C noxious weed cheatgrass.



Photo 4. Looking west from wellbore. See photo 3 comments.



Inspection Photos
Location Name: MILLER X #31-03
Location ID: 422767



Photo 5. Looking south from wellbore. See photo 3 comments.



Photo 6. Looking east from wellbore. The former interim area appears to have desirable vegetation establishment. The difference in vegetative coverage can be seen in this picture.



Inspection Photos
Location Name: MILLER X #31-03
Location ID: 422767



Photo 7. Picture taken on the east side of the interim disturbance area.



Photo 8. Reference vegetation to the east of well location.



Inspection Photos
Location Name: MILLER X #31-03
Location ID: 422767



Photo 9. Looking west across the former tank battery from the east side. Vegetation on location is primarily undesirable weeds such as kochia, russian thistle and list C noxious weed cheatgrass. A weather station is present on location.



Photo 10. Picture taken on the east side of location. Illustrating vegetation and ground conditions. Activity such as excavations or tilling may have occurred on location.



Inspection Photos
Location Name: MILLER X #31-03
Location ID: 422767



Photo 11. Looking east from the west side of the location. See photo 9 comments.



Photo 12. Picture taken on the west side of location. A section of the location is fenced off and monitoring equipment is present.

