

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Castle Springs Federal B Pad

Location # 335054



Jul 10, 2025 at 2:08:35 PM
CO



Jul 10, 2025 at 2:08:06 PM
CO

Photo # 1028 From entrance to location

Photo # 1029 From entrance to location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Castle Springs Federal B Pad

Location # 335054



Photo # 1030 Location



Photo # 1031 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Castle Springs Federal B Pad

Location # 335054



Photo # 1032 Location



Photo # 1033 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Castle Springs Federal B Pad

Location # 335054



Jul 10, 2025 at 2:20:00 PM
CO



Jul 10, 2025 at 2:24:34 PM
CO

Photo # 1034 Location

Photo # 1035 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Castle Springs Federal B Pad

Location # 335054



Photo # 5853 From inspection 708906068 conducted on 03/20/2025 PRV vent line does not comply with CECMC pressure safety device rules

Photo # 1036 PRV vent line does not comply with CECMC pressure safety device rules

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Castle Springs Federal B Pad

Location # 335054



Photo # 5854 From inspection 708906068 conducted on 03/20/2025 PRV vent line does not comply with CECMC pressure safety device rules

Photo # 1037 PRV vent line does not comply with CECMC pressure safety device rules

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Castle Springs Federal B Pad

Location # 335054



Photo # 5855 From inspection 708906068 conducted on 03/20/2025 PRV vent line does not comply with CECMC pressure safety device rules

Photo # 1038 PRV vent line does not comply with CECMC pressure safety device rules

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Castle Springs Federal B Pad

Location # 335054



Photo # 5856 From inspection 708906068 conducted on 03/20/2025 PRV vent line does not comply with CECMC pressure safety device rules

Photo # 1039 PRV vent line does not comply with CECMC pressure safety device rules

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Castle Springs Federal B Pad

Location # 335054



Photo # 5857 From inspection 708906068 conducted on 03/20/2025 Unused equipment

Photo # 1040 Unused equipment

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Castle Springs Federal B Pad

Location # 335054



Photo # 5859 From inspection 708906068 conducted on 03/20/2025 Open ended load line

Photo # 1041 Open ended load line

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Castle Springs Federal B Pad

Location # 335054



Photo # 1042 Debris



Photo # 1043 Emergency # on tank label disconnected/not in service

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Castle Springs Federal B Pad

Location # 335054



Photo # 1044 Emergency # on tank label disconnected/not in service

Photo # 1045 Emergency # on tank label disconnected/not in service