

Inspection Photos

API: 061-06838

Operator: INVESTMENT EQUIPMENT LLC

Inspection Date: 7/15/2025

County: KIOWA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast toward the location. The H₂S wind sock has been installed.



Inspection Photos



Photo 2. Facing toward the tank battery. There is a new recent spill that has occurred which will need to be reported and cleaned up.



Inspection Photos



Photo 3. View of inside the containment shows signs of a recent spill with oily freestanding liquids shown at red arrow.



Inspection Photos



Photo 4. Facing northwest at the backside of the tank battery.



Inspection Photos



Photo 5. Facing north toward the tabk battery.



Inspection Photos



Photo 6. Facing west at the location. The pile of contaminated soils have been removed. The area at red arrow has not been reclaimed.

