

Inspection Photos
Cosslet A 9 Flowline
Spill ID 478542/Remediation Project No 18952



Photo 1 – Location photo. Downed fencing/weeds.



Photo 2 - Downed fencing/weeds.



Inspection Photos
Cosslet A 9 Flowline
Spill ID 478542/Remediation Project No 18952



Photo 3 – Open excavation. Sheen observed on groundwater. Hydrocarbon impacts visible on north excavation sidewall. Downed fencing/weeds.



Photo 4 - Hydrocarbon impacts visible on north excavation sidewall.

Inspection Photos
Cosslet A 9 Flowline
Spill ID 478542/Remediation Project No 18952



**Photo 5 – Impacts visible within open excavation.
Free product was observed pooling on soil next to
groundwater. Weeds.**



**Photo 6 - Impacts and free product in open
excavation.**

Inspection Photos
Cosslet A 9 Flowline
Spill ID 478542/Remediation Project No 18952



Photo 7 – Impacts and free product in open excavation. Sheen visible on groundwater.



Photo 8 - Open excavation. Hydrocarbon impacts visible on south excavation sidewall. Downed fencing/weeds.

Inspection Photos
Cosslet A 9 Flowline
Spill ID 478542/Remediation Project No 18952



Photo 9 – Open excavation with weeds. Impacts visible below pipeline.



Photo 10 - Open excavation with weeds. Impacts visible below pipeline.

**Inspection Photos
Cosslet A 9 Flowline
Spill ID 478542/Remediation Project No 18952**



Photo 11 – Contaminated stockpile. Inadequate BMPs. Weeds.



Photo 12 - Contaminated stockpile. Inadequate BMPs. Weeds.

Inspection Photos
Cosslet A 9 Flowline
Spill ID 478542/Remediation Project No 18952



Photo 13 – Contaminated stockpile. Inadequate BMPs with torn liner and observed sediment transport. Weeds.



Photo 14 - Contaminated stockpile. Inadequate BMPs; observed sediment transport. Weeds.

Inspection Photos
Cosslet A 9 Flowline
Spill ID 478542/Remediation Project No 18952



Photo 15 – Contaminated stockpile. Inadequate BMPs; observed sediment transport. Weeds.



Photo 16 - Contaminated stockpile. Inadequate BMPs; observed sediment transport & torn liner. Weeds.

Inspection Photos
Cosslet A 9 Flowline
Spill ID 478542/Remediation Project No 18952



Photo 17 – Contaminated stockpile. Inadequate BMPs; observed sediment transport. Weeds.



Photo 18 - Contaminated stockpile. Inadequate BMPs; observed sediment transport. Weeds.

Inspection Photos
Cosslet A 9 Flowline
Spill ID 478542/Remediation Project No 18952



Photo 19 – Contaminated stockpile. Inadequate BMPs. Weeds.



Photo 20 - Contaminated stockpile. Inadequate BMPs. Weeds.

Inspection Photos
Cosslet A 9 Flowline
Spill ID 478542/Remediation Project No 18952



Photo 21 – Contaminated stockpile. Inadequate BMPs; observed sediment transport. Weeds.



Photo 22 - Contaminated stockpile. Inadequate BMPs; observed sediment transport. Weeds.

