

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/02/2025

Submitted Date:

07/10/2025

Document Number:

701104215**FIELD INSPECTION FORM**Loc ID 334955 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261850	WELL	PR	04/16/2002	GW	045-07987	PA 333-33	EG
262387	WELL	PR	04/06/2002	GW	045-08021	PA 34-33	EG
270458	WELL	PR	06/21/2004	GW	045-09561	PA 533-33	EG
270460	WELL	PR	06/10/2004	GW	045-09560	PA 433-33	EG

General Comment:

Flowline Integrity Inspection and Tank Integrity Inspection

Out of service line at separators is missing OUT OF SERVICE LOCKS AND TAGS (OOSLAT).

Location**Lease Road:**

Type			
comment:			
Corrective ActionL		Date:	

Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

--	--	--	--

Inspected Facilities				
Facility ID: 261850	Type: WELL	API Number: 045-07987	Status: PR	Insp. Status: EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 262387	Type: WELL	API Number: 045-08021	Status: PR	Insp. Status: EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 270458	Type: WELL	API Number: 045-09561	Status: PR	Insp. Status: EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 270460	Type: WELL	API Number: 045-09560	Status: PR	Insp. Status: EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404275573	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7136777
701104216	Flowline integrity inspection 701104215 photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7136775