

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/20/2025

Submitted Date:

07/11/2025

Document Number:

718800499**FIELD INSPECTION FORM**Loc ID 418322 Inspector Name: Mitchem, Katelyn On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1099 18TH STREET SUITE 1500City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                                     | Comment |
|--------------|-------|---|---------|
| ,            |       | rbucogccinspectionreports@c<br>hevron.com |         |

**Inspected Facilities:**

| Facility ID | Type     | Status | Status Date | Well Class | API Num   | Facility Name  | Insp Status |
|-------------|----------|--------|-------------|------------|-----------|----------------|-------------|
| 418322      | LOCATION | CL     |             |            | -         | Cannon X 02-29 | RI          |
| 418324      | WELL     | PA     | 03/22/2016  | OW         | 123-31900 | CANNON X 02-29 | RI          |

**General Comment:**

This is a final reclamation inspection at PA Well API# 123-31900. The well was plugged and abandoned on 03/02/2016. The associated tank battery has been inspected separately under Location ID# 418280.

|  |   |        |  |                 |  |
|--|---|--------|--|-----------------|--|
| Location   |   |        |  |                 |  |
| Overall Good: <input type="checkbox"/>                 |   |        |  |                 |  |
| Emergency Contact Number:                              |   |        |  |                 |  |
| Comment:   |   |        |  | Date: _____     |  |
| Corrective Action:                                     |   |        |  |                 |  |
| Overall Good: <input type="checkbox"/>                 |   |        |  |                 |  |
| <b>Spills:</b>   |   |        |  |                 |  |
| Type   | Area  | Volume |  |                 |  |
| In Containment: No                                     |   |        |  |                 |  |
| Comment:   |   |        |  |                 |  |
| <input type="checkbox"/> Multiple Spills and Releases? |   |        |  |                 |  |
| <b>Fencing/:</b>                                       |   |        |  |                 |  |
| Type   |   |        |  |                 |  |
| Comment:   | Fencing remains at the well location and is in disrepair. Weed debris in the form of Russian thistle (Salsola tragus) was observed across the fence line. |        |  |                 |  |
| Corrective Action:                                     | Remove fencing or ensure fencing is in proper working condition.  |        |  | Date:           |  |
| <b>Equipment:</b>                                      |   |        |  |                 |  |
| Type:  |   | #      |  | corrective date |  |
| Comment:   | No visual evidence of oil and gas equipment at the location. Refer to the attached inspection photos.   |        |  |                 |  |
| Corrective Action:                                     |   |        |  | Date:           |  |
| <b>Venting:</b>  |   |        |  |                 |  |
| Yes/No   |   |        |  |                 |  |
| Comment:   |   |        |  |                 |  |
| Corrective Action:                                     |   |        |  | Date:           |  |
| <b>Flaring:</b>  |   |        |  |                 |  |
| Type   |   |        |  |                 |  |
| Comment:   |   |        |  |                 |  |
| Corrective Action:                                     |   |        |  | Date:           |  |

| Inspected Facilities   |        |       |          |             |           |         |    |               |    |
|--|--------|-------|----------|-------------|-----------|---------|----|---------------|----|
| Facility ID:   | 418322 | Type: | LOCATION | API Number: | -         | Status: | CL | Insp. Status: | RI |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |       |          |             |           |         |    |               |    |
| Facility ID:   | 418324 | Type: | WELL     | API Number: | 123-31900 | Status: | PA | Insp. Status: | RI |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |       |          |             |           |         |    |               |    |

| Environmental   |                              |                               |       |
|---|------------------------------|-------------------------------|-------|
| <b>Spills/Releases:</b>   |                              |                               |       |
| Type of Spill: _____  |                              | Estimated Spill Volume: _____ |       |
| Comment: <div>There are no reported spills or remediation projects for the well location.</div> |                              |                               |       |
| Corrective Action: _____  |                              | Date: _____                   |       |
| Reportable: _____   | GPS: Lat _____               | Long _____                    |       |
| Proximity to Surface Water: _____   | Depth to Ground Water: _____ |                               |       |
| <b>Water Well Complaint:</b>  |                              |                               |       |
|   |                              | Lat                           | Long  |
| DWR Receipt Num: _____  | Owner Name: _____            | GPS :                         | _____ |
| <b>Field Parameters:</b>  |                              |                               |       |
|   |                              |                               |       |
| Sample Location: _____  |                              | Comment: _____                |       |

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: RANGELAND

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

- 1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_
- 1003c. Compacted areas have been cross ripped? \_\_\_\_\_
- 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_
- Cuttings management: \_\_\_\_\_
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_
- Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: RANGELAND

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged Pass Pit mouse/rat holes, cellars backfilled Pass

Debris removed Pass No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded Pass Contoured Pass Culverts removed Pass

Gravel removed Pass

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% Fail Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: This location does not meet reclamation regulations as there is insufficient vegetative cover. Comply with 1004 rules to establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels.

Corrective Action: Comply with Rule 1004 to perform additional reclamation activities at the well location and along the access road.

Date \_\_\_\_\_

Overall Final Reclamation **Fail** Well Release on Active Location ☐ Multi-Well Location ☐**Storm Water:**

| Loc Erosion BMPs   | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment                    |
|--|-----------------|-------------------------|-----------------------|---------------|--------------------------|----------------------------|
|  |                 |                         |                       |               |                          |                            |
| Comment: <input type="text" value="At the time of this inspection, no stormwater erosion issues were observed at the location or along the access road."/> |                 |                         |                       |               |                          |                            |
| Corrective Action: <input type="text"/>  |                 |                         |                       |               |                          | Date: <input type="text"/> |
| Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT  |                 |                         |                       |               |                          |                            |

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 404277153    | INSPECTION SUBMITTED | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7138791">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7138791</a> |
| 718800500    | Inspection Photos    | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7138753">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7138753</a> |