

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/25/2025

Submitted Date:

07/11/2025

Document Number:

699700476

**FIELD INSPECTION FORM**Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
Heil, John 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10539

Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP

Address: 734 MAIN STREET 3RD FLOOR

City: GRAND JUNCTION State: CO Zip: 81501

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,	970-675-7928	inspections@utahgascorp.com	<a href="#">All Inspections</a>
Roberts, James		j75rober@blm.gov	<a href="#">BLM meeker</a>
Cholas, Nick		nick.cholas@state.co.us	
Pollack, Dana		dpollack@utahgascorp.com	<a href="#">Environmental Specialist II</a>
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
45072	LEASE	PR	05/08/1996		-	FEDERAL D-22-3-101-W	EI

**General Comment:**[ECMC Environmental Inspection.](#)

Inspected Facilities									
Facility ID:	45072	Type:	LEASE	API Number:	-	Status:	PR	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

**Environmental****Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: \_\_\_\_\_

Comment: See Initial Form 19 Doc #404252800 and Supplemental Form 19 Doc #404267391 for more information. ECMC staff John Heil conducted an Environmental Inspection of the point of release as well as the potentially impacted stock pond. Fluids within the potentially impacted stock pond had been removed by the operator and fresh water was trucked in for wildlife and was placed in a stock pond adjacent to the potentially impacted stock pond. Operator personnel were on location at time of inspection removing any residual fluids that accumulated in the base of the potentially impacted stock pond. ECMC did not observe any hydrocarbon sheen, staining or odor within the potentially impacted stock pond. Evidence of wildlife was observed within the potentially impacted stock pond and the operator was contacted via cellphone on June 25, 2025. ECMC environmental staff advised the operator to implement BMPs to minimize the impacts to wildlife within the potentially impacted stock pond. See attached Photo Log for details.

Corrective Action: **Comply with COAs on Form 19 Initial Doc #404252800.**

Date: \_\_\_\_\_

Reportable: YES

GPS: Lat \_\_\_\_\_

Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat

Long

DWR Receipt Num: \_\_\_\_\_

Owner Name: \_\_\_\_\_

GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Comment: \_\_\_\_\_

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404276841	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7138451">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7138451</a>
699700477	20250625 Photo Log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7138442">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7138442</a>