

Inspection Photos

API:061-05138

Operator: WESTERN OPERATING COMPANY

Inspection Date: 7/15/2025

County: KIOWA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast along the access road. The road needs to be recontoured to original grade and reclaimed.



Inspection Photos



Photo 2. Facing north along the access road. The road needs to be recontoured to original grade and reclaimed.



Inspection Photos



Photo 3. Facing north at the recontoured portion of the road.



Inspection Photos



Photo 4. Facing northwest toward the location. There is some perennial vegetation establishing. Undesirable weeds need to be controlled.



Inspection Photos



Photo 5. Drone aerial photo facing north overlooking the reclaimed portion of the road and location.



Inspection Photos



Photo 6. Drone aerial photo facing northwest toward the location.



Inspection Photos



Photo 7. Drone aerial photo facing northeast toward the location. The dark green vegetation is mostly undesirable weeds (Kochia) which needs to be controlled.



Inspection Photos



Photo 8. Drone aerial photo facing northeast at the location.



Inspection Photos



Photo 9. Drone aerial photo facing south toward the reclaimed access road.

