

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK 7314

Location ID: 315141

Date: 07/15/2025



Photo # 9982 Entrance to location



Photo # 0003 Location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK 7314

Location ID: 315141

Date: 07/15/2025



Photo # 9983 Location



Photo # 9989 Location



## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK 7314

Location ID: 315141

Date: 07/15/2025



Photo # 0019 SE corner of location



Photo # 0020 SW corner of location



## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK 7314

Location ID: 315141

Date: 07/15/2025



Photo # 0021 NW corner of location



Photo # 0022 NE corner of location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK 7314

Location ID: 315141

Date: 07/15/2025



**Photo # 9986 Wellhead sign lacks required information/not in compliance with CECMC rules**



**Photo # 9998 Hole in separator building open to wildlife/available for entry by wildlife**



## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK 7314

Location ID: 315141

Date: 07/15/2025



**Photo # 9999 Separator heater open to wildlife/available for entry by wildlife**



**Photo # 0012 Subsidence on SE side of location, additionally is a wildlife hazard/personnel safety hazard**



## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK 7314

Location ID: 315141

Date: 07/15/2025



**Photo # 0028 Subsidence on SE side of location, additionally is a wildlife hazard/personnel safety hazard**



**Photo # 0010 Debris on location**



## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK 7314

Location ID: 315141

Date: 07/15/2025



Photo # 0011 Debris on location

