

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/09/2025

Submitted Date:

07/14/2025

Document Number:

719500190**FIELD INSPECTION FORM**Loc ID 334977 Inspector Name: Morris, Matthew On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10844Name of Operator: QB ENERGY OPERATING LLCAddress: 1001 17TH STREET SUITE 1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Energy, QB		ecmc.inspections@qb-energy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258990	WELL	PR	01/01/2024	GW	045-07678	PUCKETT 13-6D	PR
258991	WELL	PR	01/01/2024	GW	045-07679	PUCKETT 23-6D	PR
259001	WELL	PR	01/01/2024	GW	045-07681	PUCKETT 41-12D	PR
259002	WELL	SI	05/01/2024	GW	045-07682	PUCKETT 44-1D	SI
259003	WELL	PR	01/01/2024	GW	045-07683	PUCKETT 42-12D	PR
259004	WELL	PR	01/01/2024	GW	045-07670	PUCKETT 14-6D	PR

**General Comment:****CECMC Audit Report Summary**

On 7/9/2025 at approximately 12:40, Compliance Inspector Matthew Morris conducted a follow-up audit at QB ENERGY OPERATING LLC, PUCKETT-67S96W/6SWNW at Location ID #334977 in Garfield County, Colorado.

During the audit, the following compliance issues were observed:

- 1) Damaged/unserviceable wildlife netting on methanol tank containment

A follow-up on this site audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment: 911/(970)285-2615

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Barbed wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Pipe rails		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbed wire		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:			Date:
Type: Gas Meter Run	# 7		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 6		
Comment:			
Corrective Action:			Date:
Type: Dehydrator	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Liquid nitrogen tank		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 6		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 7		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	500 gal
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				
Comment:	Damaged/unserviceable wildlife netting on tank containment.			
Corrective Action:	Comply with CECMC wildlife safety rules.			Date: 07/30/2025

Contents	#	Capacity	Type	Tank ID	SE GPS	
GLYCOL	1	OTHER	STEEL AST		,	
Comment:						
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)		500 gal				
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal						
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal						
Comment:						
Corrective Action:						Date:
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:						Date:

**Inspected Facilities**Facility ID: 258990 Type: WELL API Number: 045-07678 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: 

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 258991 Type: WELL API Number: 045-07679 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: 

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 259001 Type: WELL API Number: 045-07681 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: 

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 259002 Type: WELL API Number: 045-07682 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: Comment: Last produced April 2025 per production report.Corrective Action: Date: 

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 259003 Type: WELL API Number: 045-07683 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: 

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 259004 Type: WELL API Number: 045-07670 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: 

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
Ditches						
		Ditches				
		Sediment Traps				
		Check Dams				
		Culverts				
		Gravel				
		Rip Rap				
				Material Handling And Spill Prevention		
Berms						
		Compaction				
Compaction						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404278278	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7140542">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7140542</a>
719500191	Photo Log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7140537">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7140537</a>