

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/14/2025

Submitted Date:

07/14/2025

Document Number:

713302157**FIELD INSPECTION FORM**Loc ID 319935 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KPK	303-825-4822	cogcc@kpk.com	<a href="#">all inspections</a>
Medina, Justin		justin.medina@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201933	WELL	PR	06/01/2021	GW	001-07337	UPRR 24 PAN AM C 2	PR

**General Comment:**[well site inspection](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

<b>Good Housekeeping:</b>		
Type	WEEDS	
Comment:	overgrown vegetation, complete well site, all photos	
Corrective Action:	Comply with Rul 606	Date: 07/21/2025

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>		
Type	WELLHEAD	
Comment:	pipe guard	
Corrective Action:		Date:

<b>Equipment:</b>			corrective date
Type: Plunger Lift	#		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	pipd to surface		
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	automation		
Corrective Action:		Date:	

<b>Venting:</b>		
Yes/No	NO	
Comment:		
Corrective Action:		Date:

<b>Flaring:</b>	
Type	

Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 201933 Type: WELL API Number: 001-07337 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITEComment: Valves appeared to be closed at time of inspectionCorrective Action:  Date: **BradenHead**Date of Last Brhd Test: 08/13/2024 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action:  Date: 

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
Inspector Michael Kester, did audit scout card and related documents conducted well-site inspection, Location: UPRR 24 Pan Am C 2 Operator: KPK API#: 001-07337 County: Adams While there, I observed well site, During this inspection the following possible compliance issues were observed:  Overgrown vegataion, Rule 606 corrective action date 7-21-2025 all photos  Weather conditions: sunny and dry  A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules. This inspection does not nullify any orders or NOAV from the ECMC	kesterm	07/14/2025

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404278621	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7140847">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7140847</a>
713302158	site pic	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7140841">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7140841</a>