

Final Reclamation and Stormwater Inspection

July 18, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 320364

Well Name: DREYER #1

Inspection Document #: 718600798

Adams County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: DREYER #1
Location ID: 320364



Photo 1. Looking west across the location. Desirable vegetation is present on location but appears to have a coverage lower than the surrounding reference area.



Photo 2. Photo taken on the access road near the location. A relatively high amount of gravel remains on location and may be affecting establishment of desirable vegetation.

Inspection Photos
Location Name: DREYER #1
Location ID: 320364



Photo 3. Photo taken on the north side of the location looking north. Illustrating reference vegetation on the right and disturbance area on the left. Vegetation on location does not appear to have reached 80% coverage of the reference area.



Photo 4. Looking west from the wellbore. No oil and gas equipment remains. Desirable vegetation is present on location but does not appear to have reached 80% coverage of the reference area.



Inspection Photos
Location Name: DREYER #1
Location ID: 320364



Photo 5. Looking south from the center of the location. See photo 4 comments.



Photo 6. Looking east from the center of the location. See photo 4 comments.



Inspection Photos
Location Name: DREYER #1
Location ID: 320364



Photo 7. Looking north from the center of the location. List C noxious weed mullein is present on location.



Photo 8. Reference vegetation to the south of the location. Reference vegetation is relatively high quality, consisting of salt grass and western wheatgrass.