

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/15/2025

Submitted Date:

07/21/2025

Document Number:

708906928**FIELD INSPECTION FORM**Loc ID 311543 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10550Name of Operator: MUSTANG RESOURCES LLCAddress: 3 GREENWAY PLAZA STE 1360City: HOUSTON State: TX Zip: 77046**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**14 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Toews, Wesley		wtoews@blm.gov	
Mustang		nwelch@venatorresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210685	WELL	PR	07/01/2021	GW	045-06441	CLOUGH FEDERAL 14-24A-6S-94W	PR

**General Comment:****CECMC Inspection/Audit Report Summary**

On 07/15/2025 at approximately 11:34 hours, I, Compliance Specialist, Wayne Smelser

Conducted an on-site inspection/audit at MUSTANG RESOURCES LLC CLOUGH FEDERAL 14-24A-6S-94W

Location # 311543 in Garfield County Colorado.

Location is within High Priority/Density Habitat areas &amp; in close proximity to Bald Eagle Roost Site.

While there, I observed normal production operations.

During this inspection/audit the following compliance issues were observed:

1. Equipment - PRV vent line does not comply with CECMC pressure safety device rules with a CA date of 07/28/2025
2. Tank & Berms - Multiple holes in secondary containment liner/liner needs maintenance with a CA date of 08/10/2025

A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection/audit report.

Duel lease - Shared pad with WF CLOUGH FEDERAL 14-24-6S-94W location # 311542

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	911/888-291-8588	
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Horizontal Heated Separator	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	PRV vent line does not comply with CECMC pressure safety device rules		
Corrective Action:	Comply with CECMC pressure safety device rules	Date:	07/28/2025
Type: Ancillary equipment	# 1		
Comment:	Catalytic heater		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		

Comment:	No form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible			
Corrective Action:			Date:	
Type: Plunger Lift	# 1			
Comment:	Well on plunger lift			
Corrective Action:			Date:	
Type: Deadman # & Marked	# 5			
Comment:	Marked			
Corrective Action:			Date:	
Type: Gas Meter Run	# 2			
Comment:				
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLs	STEEL AST		,	
Comment:	Tank not equipped with telemetry					
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate		Base Insufficient	Inadequate
Comment:	Multiple holes in secondary containment liner/liner needs maintenance			
Corrective Action:	The liner will be sufficiently impervious so that any discharge from a primary containment system will not escape containment before cleanup occurs.			Date: 08/10/2025

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	210685	Type:	WELL	API Number:	045-06441	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						Sparse to none in most areas
		Ditches				
		Gravel				Sparse to none in sections
		Culverts				
Berms						
		Compaction				
Compaction						Light compaction in some areas

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
Please refer to Equipment & Tanks & Berms for corrective actions.	smelserw	07/21/2025
Duel lease - Shared pad with WF CLOUGH FEDERAL 14-24-6S-94W location # 311542		

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404288439	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7152893">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7152893</a>
708906929	Inspection/Audit 708906928 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7152887">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7152887</a>
708906930	Inspection/Audit 708906928 Stormwater photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7152888">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7152888</a>