

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/09/2025

Submitted Date:

07/21/2025

Document Number:

719000290**FIELD INSPECTION FORM**Loc ID 334337 Inspector Name: GARCIA, CHARLES On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10464Name of Operator: CATAMOUNT ENERGY PARTNERS LLCAddress: 600 17TH STREET STE 1400SCity: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, General		Inspections@catamountep.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275690	WELL	SI	06/01/2021	OBW	067-09008	SECORD 17U-34-6 1X	SI
275691	WELL	PR	01/01/2024	CBM	067-09009	Secord 17U 34-6 1	PR
455301	WELL	PR	10/01/2021	CBM	067-10023	Secord 17U 34-6 3	PR
455302	WELL	PR	10/19/2021	CBM	067-10024	Secord 17U-34-6 2	PR

General Comment:

Inspection Report Summary
 On 07/18/25 I Inspector Charles Garcia
 conducted an on-site inspection.
 Location: SECORD 17U-34-6 #1X, 17U-34-6#1, 17U-34-6#2, 17U-34-6#3
 Operator: CATAMOUNT ENERGY PARTNERS LLC
 API#067-09008
 API#067-09009
 API#067-10023
 API#067-10024
 County: LaPlata

LocationOverall Good: ☒**Signs/Marker:**

Type	OTHER		
Comment:	LOCATION SIGN AT ENTERANCE		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	970-442-6620 911 EMERGENCY	
Corrective Action:		Date:

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type:				corrective date
Type: Flow Line	# 3			
Comment:				
Corrective Action:				Date:
Type: Bird Protectors	# 3			
Comment:				
Corrective Action:				Date:
Type: Other	# 4			
Comment:	WELLHEADS			
Corrective Action:				Date:
Type: Prime Mover	# 3			
Comment:	GAS			
Corrective Action:				Date:
Type: Bradenhead	# 3			
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 3			
Comment:				
Corrective Action:				Date:
Type: Pump Jack	# 3			
Comment:				
Corrective Action:				Date:
Type: Deadman # & Marked	# 1			
Comment:	NO MARKER			

Corrective Action:		Date:	
Type: Ancillary equipment	# 4		
Comment:	TELEMETRY EQUIPMENT CHEMICAL INJECTION CONTAINER WITH SPILL PREVENTION		
Corrective Action:		Date:	
Type: Gas Meter Run	# 3		
Comment:	CALIBRATION IN COMPLIANCE		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 275690 Type: WELL API Number: 067-09008 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: PER RULE 417 PREFORM MIT WITHIN 30 DAYS SEE WARNING LETTER DOCUMENT #402183776 SENT TO PREVIOUS OPORATOR ON 9/20/19

Corrective Action: PREFORM MIT PER RULE 417

Date: 08/21/2025

BradenHead

Date of Last Brhd Test: 12/19/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 275691 Type: WELL API Number: 067-09009 Status: PR Insp. Status: PR

Producing Well

Comment: _____

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 06/26/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 455301 Type: WELL API Number: 067-10023 Status: PR Insp. Status: PR

Producing Well

Comment: _____

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 06/17/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 13 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 455302 Type: WELL API Number: 067-10024 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:			Date:

BradenHead			
Date of Last Brhd Test:	12/19/2024	Annual Brhd Completed?	Yes
Last Brhd Test Results	Initial Surf Csg Pressure: 4	Fluid Type:	
	End Surf Csg Pressure: 0		
Comment:			
Corrective Action:			Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404287296	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7151680
719000347	LOCATION PICTURES	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7151667