

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/15/2025

Submitted Date:

07/23/2025

Document Number:

718300042

**FIELD INSPECTION FORM**

Loc ID 331151 Inspector Name: Anderson, Laurel On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 83130  
Name of Operator: STRACHAN EXPLORATION INC  
Address: 992 S 4TH AVE SUITE 100-461  
City: BRIGHTON State: CO Zip: 80601

**Findings:**

- 9 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Harms, Jason	303-330-1921	jason@strachanexploration.com	
, Justin		Justin@strachanexploration.com	Strachan Exploration
Strachan, Stephen	(303) 785-7006	sms@strachanexploration.com	
Petrie, Erica		erica.petrie@state.co.us	
L, Stacy		stacy@strachanexploration.com	Field inspections
Binschus, Chris		chris.binschus@state.co.us	
Heibel, Krystal		krystal.heibel@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258930	WELL	PR	01/01/2022	GW	123-20234	FEDERAL TOUCAN 28-14	PR
331151	LOCATION	AC			-	FEDERAL TOUCAN-68N60W 28SESW	EI

**General Comment:**

On July 15th, 2025, ECMC Environmental Protection Specialist Laurel Anderson performed a routine environmental inspection of the Federal Toucan 28-14 well (Location ID 331151/ API 123-20234). Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Operator: STRACHAN EXPLORATION INC (Operator No: 83130)  
-Location Name: Federal Toucan 28-14 well (Location ID 331151/ API 123-20234)

Location is within: US Forest Service (USFS) Pawnee National Grassland, grazing land and a mapped CPW Ferruginous Hawk Active Nest Site High Priority Habitat buffer.

Location is within 0.5 miles of a water well.

Current site status:

- Signage at the well was adequate (Photo 1)
- Weeds observed on well pad surface (Photos 2 & 7).
- Barbed wire fencing has been installed around the well and pumping unit; however, fencing requires maintenance - Access gate was open and the southern stretch of fencing was down at the time of inspection. Livestock footprints and manure were observed throughout the location both inside and outside the fenced area (Photos 2-7).
- A ~5-gallon bucket with oily waste was observed in the pumping unit engine shed - The bucket was tipped over and stained soil was observed below (Photos 4 & 5).

<b>Location</b>			
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Adequate.		Date: _____
Corrective Action:			
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Weeds observed on well pad surface (Photos 2 & 7).		
Corrective Action:	Comply with Rule 606.c.		Date: <u>08/06/2025</u>
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
Comment:	Stained soil observed on the well pad and beneath a tipped over ~5-gallon bucket of oily waste located within the pumping unit engine shed. See Photos 3-7.		
Corrective Action:	Investigate and clean up stained soil, maintaining records, reporting as appropriate, and properly manage E&P Waste in accordance with 900 Series Rules. Operator shall properly store and dispose of waste. For E&P waste: Properly dispose of oily E&P waste in accordance with 905.e. For non E&P waste: Handle waste in accordance with Rule 906 and conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.f.(2).D.		Date: <u>07/24/2025</u>
In Containment: No _____			
Comment: _____			
<input checked="" type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Barbed wire fencing has been installed around the well and pumping unit; however, fencing requires maintenance - Access gate was open and the southern stretch of fencing was down at the time of inspection. Livestock footprints and manure were observed throughout the location both inside and outside the fenced area (Photos 2-7). Fencing is no longer adequate/effective at excluding entry of people, livestock or wildlife at time of inspection.		
Corrective Action:	Operator shall immediately install, repair and maintain best management practices to protect the environment, public health, safety and welfare and the environment as required by Rule 913.b.(5)B.i and ECMC Guidance 913.b.(5)B i-v which requires fencing used be appropriate to site conditions, ie: nearby residences, depth of excavation, presence of ground or surface water, livestock, wind, etc.		Date: <u>07/24/2025</u>
<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:			Date:
<b>Flaring:</b>			

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 258930 Type: WELL API Number: 123-20234 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 331151 Type: LOCATION API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
Follow up inspection required Weather: Partly Cloudy, 90F, Slight breeze PPE: Level D + FR	andersoln	07/23/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404291050	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7155708">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7155708</a>
718300043	2025_0715_Federal Toucan 28-14 Well Photo Log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7155699">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7155699</a>