32-567

CEMENTER'S RECEIVED SERVICE, INC.

P.O. BOX 336220 • GREELEY, CO 80633 • (970) 353-7289 • FAX (970) 353-7712

OCT 28 2010

OUR INVOICE

198509

(PO.# 79887)

Date 10-17-10	Well Owner PDC	Well No. 21KDU	Lease CENTENNIAL
County WELD	State COLORADO		Field
Charge to ENSIGN US DRILLING			Charge Code
Address PO BOX 17805 (ENSIGN-32)			For Office Use Only
City, State DENVER COLORADO 80217			
Pump Truck No. 1202	Code	Bulk Truck No. 1207	Code
Type of Job		Depth Ft. 705	To
(Surface) 8 5/8" CSG - 24#		Bottom of Surface Ft. 693	To
Plug		Plug Landed @ 678 Ft.	Time On 0015
Production		Pipe Landed @ 693 Ft.	Time Off PLUG DOWN 0315

Reference No.	Description		Qty.	Meas.	Unit Pr
	Pump Truck Charge				
	Cement Neat ✓		490	SKS	
	Poz. Mix				
	Calcium Chloride		3%		
	Gel % Flo-Cele ¼ #Per Sack				
	Handling Charge				
	Hauling Charge				
	Additional Cement				
	MIX RATE 4 BPM	SLURRY VOL	1.18		FT³/SK
	DISP. RATE 5 BPM	SLURRY WT	15.2		PPG
	PLUG LANDED @ 220 PSI	TOTAL SLURRY VOL	103 B		
		WATER TEMP	60 °F		

Remarks			
PREFLUSH W/ 20 BBL H20	Tax Reference Code		Sub Total
DISPLACE W/ 43 BBL H20	State CO 2.9 %		Tax
CIRCULATE 10 BBL CEMENT	Disc.		Total

Truck No.	Code	State Mileage	Nebraska	Colorado	Wyoming	C
1202		Pump Truck		40		
1207		Bulk Truck		40		

We do not assume any responsibility for any damage or conditions resulting from our services. All pricing is subject to

Delivered By Joe, Josh, Kerry

Received By

Customer or His Agent