Rig 32

CEMENTER'S WELL SERVICE, INC.

P.O. BOX 338220 • GREELEY, CO 80633 • (970) 353-7299 • FAX (970) 353-7712

OUR INVOICE

198789

(P.O.# 95551)

Date 12-24-10	Well Owner PDC	Well No. 11-10D4	Lease BRADER
County WELD	State COLORADO		Field
Charge to ENSIGN USA DRILLING			Charge Code
Address P.O. BOX 17805 (ENSIGN #32)			For Office Use Only
City, State DENVER CO. 80217			

Pump Truck No. 1201	Code	Bulk Truck No. 1214	Code		
Type of Job		Depth	Ft. 475	To	
Surface 9 5/8" CSG 24#		Bottom of Surface	Ft. 464	To	
Plug		Plug Landed @ 444 Ft.	Time On 0730		
Production		Pipe Landed @ 464 Ft.	Time Off PLUG DOWN 0915		

Reference No.	Description	Qty.	Meas.	Unit Pric
	Pump Truck Charge			
	Cement Neat ✓	350	SKS	
	Poz. Mix			
	Calcium Chloride	3%		
	Gel % Flo-Cele 1/4 #Per Sack			
	Handling Charge			
	Hauling Charge			
	Additional Cement			
	TATAL SLURRY VOL 73.5 BBLS CEMENT PLUG LANDED @ 250PS			
	MIX RATE 4BPM/DISP. RATE 5 BPM			
	SLURRY VOL 1.18 CUFT/SK - SLURRY WT 14.8-15 PPG			

Remarks: PRE-FLUSH W/ 10 BBLS H_2O	Tax Reference Code	Sub Total	
DISPLACE W/ 29 BBLS H_2O	State CO 2.9 %	Tax	
CIRCULATE 5 BBLS CEMENT	Disc.	Total	

Truck No.	Code	State Mileage	Nebraska	Colorado	Wyoming	C
1201		Pump Truck		30		
1214		Bulk Truck		30		

We do not assume any responsibility for any damage or conditions resulting from our services. All pricing is subject to

Delivered By JIM, OSCAR, STEVE

Received By _____

Customer or His Agent