CEMENTER'S WELL SERVICE, INC.

P.O. BOX 338220 • GREELEY, CO 80633 • (970) 353-7299 • FAX (970) 353-7712

Rig 32

OUR INVOICE

198793

P.O.# (96497)

Date 12/31/10	Well Owner PDC	Well No. 12-10DU	Lease Binder
County Weld	State Colorado		Field
Charge to ENSIGN US Drilling			Charge Code
Address P.O. Box 17805 (Ensign #32)			For Office Use Only
City, State Denver, Colorado 80917			
Pump Truck No. 1208	Code	Bulk Truck No. 1217	Code
Type of Job		Depth	Ft. 479 To
Surface 8 5/8" CSG - 24#		Bottom of Surface	Ft. 469 To
Plug		Plug Landed @ 454 Ft.	Time On 0615
Production		Pipe Landed @ 469 Ft.	Time Off Plug Down @ 0930

Reference No.	Description	Qty.	Meas.	Unit Price	Amount
	Pump Truck Charge				
	Cement Neat	330	SKS		
	Poz. Mix				
	Calcium Chloride	3%			
	Gel % Flo-Cele # #Per Sack				
	Handling Charge				
	Hauling Charge				
	Additional Cement				
	Mixing Rate - 4 BPM / Displacement Rate - 4 BPM				
	Slurry Vol - 1.18 Cu FT/Sk - Slurry WT 15.2 PPG				
	Total Slurry Vol 69 BBLS Cement				
	Landed Plug @ 200 PSI / Water Temp 30° F				

Remarks: Pre-Flush w/ 15 BBLS H^{20}

Displace w/ 29 BBLS H^{20}

Circulate 3 BBLS Cement

Tax Reference Code		Sub Total
State CO 2.9 %		Tax
Disc.		Total

Truck No.	Code	State Mileage	Nebraska	Colorado	Wyoming	
1208		Pump Truck		24		
1217		Bulk Truck		24		

We do not assume any responsibility for any damage or conditions resulting from our services. All pricing is subject

Delivered By Justin, Dallas & James

Received By

Customer or His Agent