CEMENTER'S WELL SERVICE, INC.

P.O. BOX 336220 • GREELEY, CO 80633 • (970) 353-7299 • FAX (970) 353-7712

OUR INVOICE

198850

32

(P.O.# 98538)

Date 1-10-11	Well Owner PDC	Well No. 21-10DU	Lease BINDER
County WELD	State COLORADO		Field
Charge to ENSIGN US DRILLING			Charge Code
Address PO BOX 17805 (ENSIGN-32)			For Office Use Only
City, State DENUER COLORADO 80217			
Pump Truck No. 1202	Code	Bulk Truck No. 1214	Code
Type of Job		Depth	Ft. 462 To
(Surface) 8 5/8" CSG 24#		Bottom of Surface	Ft. 452 To
Plug		Plug Landed @ 437 Ft.	Time On 0145
Production		Pipe Landed @ 452 Ft.	Time Off PLUG DOWN 0400

Reference No.	Description	Qty.	Mens.	Unit Price	Amount
	Pump Truck Charge				
	Cement Neat ✓	320	SKS		
	Poz. Mix				
	Calcium Chloride	3%			
	Gel % Flo-Cele # Per Sack				
	Handling Charge				
	Hauling Charge				
	Additional Cement				
	MIX RATE 4 BPM	SLURRY VOL	1.18	FT³/SK	
	DISP RATE 5 BPM	SLURRY WT	15.2	PPG	
	PLUG LANDED @ 180 PSI	TOTAL SLURRY VOL	67		

Remarks: PREFLUSH W/ 20 BBLS H20	Tax Reference Code	Sub Total
DISPLACE W/ 27.5 BBLS H20	State CO 2.9 %	Tax
CIRCULATE 5 BBLS CEMENT	Disc.	Total

Truck No.	Code	State Mileage	Nebraska	Colorado	Wyoming	
1202		Pump Truck		36		
1214		Bulk Truck		36		

We do not assume any responsibility for any damage or conditions resulting from our services. All pricing is subject t

Delivered By Joe, Josh, KERRY

Received By Jim Flinn

Customer or His Agent