5-669

CEMENTER'S WELL SERVICE, INC.

P.O. BOX 336220 • GREELEY, CO 80633 • (970) 353-7299 • FAX (970) 353-7712

OUR INVOICE

198992

(P.O.# 109C3E)

Date 2/21/11	Well Owner PDC	Well No. 7CD	Lease Schaefer
County Weld	State Colorado		Field
Charge to ENSIGN US DRILLING			Charge Code
Address PO Box 17905 (ENSIGN #5)			For Office Use Only
City, State Denver, Colorado 80217			
Pump Truck No. 1208	Code	Bulk Truck No. 1217	Code
Type of Job		Depth	Ft. 757 To
Surface 8 5/8" CSA-94'		Bottom of Surface	Ft. 777 To
Plug		Plug Landed @ 742 Ft.	Time On 1515
Production		Pipe Landed @ 777 Ft.	Time Off Plug Down 1830

Reference No.	Description	Qty.	Meas.	Unit Price	Amount
	Pump Truck Charge				
	Cement Neat ✓	550	SKS		
	Poz. Mix				
	Calcium Chloride	3%			
	Gel % Flo-Cele ¼ #Per Sack				
	Handling Charge				
	Hauling Charge				
	Additional Cement				
	Mixing Rate-4 BPM/Displacement Rate-4 BPM				
	Slurry Vol-1.18 CU FT/SK-Slurry WT 15.2 PPG				
	Total Slurry Vol 115.5 BBLS Cement				
	Landed Plug @ 400 PSI/Water Temp 49°F				

Remarks: Pre-Flush w/ 30 BBLS H20	Tax Reference Code	Sub Total
...w/ 47 BBLS H20	State CO 2.9 %	Tax
...e 5 BBLS Cement	Disc.	Total

Truck No.	Code	State Mileage	Nebraska	Colorado	Wyoming	Other
		Pump Truck		30		
		Bulk Truck		30		

We do not assume any responsibility for any damage or conditions resulting from our services. All pricing is subject to review and revision.

Delivered By Justin Davis Travis - Weld

Received By

Customer or His Agent