32

CEMENTER'S WELL SERVICE, INC.

P.O. BOX 336220 • GREELEY, CO 80633 • (970) 353-7299 • FAX (970) 353-7712

RECD NOV 24 2010

OUR INVOICE

198671

(P.O.# 87940)

Date 11/19/10	Well Owner PDC	Well No. 10-NDU	Lease Binder
County Weld	State Colorado		Field
Charge to ENSIGN US Drilling			Charge Code
Address P.O. BOX 17805 (ENSIGN #32)			For Office Use Only
City, State Denver, Colorado 80217			
Pump Truck No. 1208	Code	Bulk Truck No. 1217	Code
Type of Job		Depth Ft. 425	To
Surface 8 5/8" CSG 24#		Bottom of Surface Ft. 416	To
Plug		Plug Landed @ 401 Ft.	Time On 0440
Production		Pipe Landed @ 416 Ft.	Time Off Plug Down 0730

Reference No.	Description	Qty.	Meas.	Unit Pr
	Pump Truck Charge			
	Cement Neat ✓	300	SKS	
	Poz. Mix			
	Calcium Chloride	3%		
	Gel % Flo-Cele 1/4 #Per Sack			
	Handling Charge			
	Hauling Charge			
	Additional Cement			
	Max Avg Rate - 7 BPM / Displacement Rate - 4 BPM			
	Slurry Vol - 1.18 CU FT/SK - Slurry Wt 15.2 PPG			
	Total Slurry Vol 43 BBLS Cement			
	Landed Plug @ 200 PSI / Water Temp 40°F			

Remarks: Pre-Flush w/15 BBLS H20

Displace w/25 BBLS H20

Circulate 4 BBLS Cement

Tax Reference Code	Sub Total
State CO 2.9 %	Tax
Disc.	Total

Truck No.	Code	State Mileage	Nebraska	Colorado	Wyoming	
1208		Pump Truck		38		
1217		Bulk Truck		38		

We do not assume any responsibility for any damage or conditions resulting from our services. All pricing is subject to

Delivered By Justin, Steve & Dallas

Received By

Customer or His Agent