
Sonic
Density
Neutron
Gamma Ray
Resistivity
Caliper
Bit Size
Mud Weight
Temperature
Lithology
Porosity
Permeability
Saturation
Fluid Contacts
Formation Tops
Core Data
Drill Stem Tests
Production Tests
Completion Intervals
Perforations
Stimulations
Remarks
Depth



WELLIBRATION

SUSSEX PASS
Z = 1.0Z

WELLIBRATION

MAIN PASS
Z = 1.0Z

WELLIBRATION

MAIN PASS
Z = 1.0Z

WELLIBRATION

LOGGING PASS
Z = 1.0Z

WELLIBRATION

LOGGING PASS
Z = 1.0Z