32-579

CEMENTER'S WELL SERVICE, INC.

P.O. BOX 338220 • GREELEY, CO 80633 • (970) 353-7299 • FAX (970) 353-7712

OUR INVOICE

198736

(P.O # 93068)

Date 12/14/10	Well Owner PDC	Well No. 10-SDU	Lease Binder
County Weld	State Colorado		Field
Charge to ENSIGN US DRILLING			Charge Code
Address P.O. Box 17805 (ENSIGN #32)			For Office Use Only
City, State Denver, Colorado 80217			
Pump Truck No. 1208	Code	Bulk Truck No. 1214	Code
Type of Job		Depth	Ft. 426 To
Surface 8 5/8" CSG-24#		Bottom of Surface	Ft. 416 To
Plug		Plug Landed @ 370	Ft. Time On 1550
Production		Pipe Landed @ 416	Ft. Time Off Plug Down 1715

Reference No.	Description	Qty.	Mess.	Unit P
	Pump Truck Charge			
	Cement Neat ✓	300	SKS	
	Poz. Mix			
	Calcium Chloride	3%		
	Gel % Flo-Cele 1/4 #Per Sack			
	Handling Charge			
	Hauling Charge			
	Additional Cement			
	Mixing Rate-4 BPM/Displacement Rate-4 BPM			
	Slurry Vol-1.18 CU FT/SK-Slurry Wt 15.2 PPG			
	Total Slurry Vol 103 BBLS Cement			
	Landed Plug @ 300 PSI/Water Temp 45°F			

Remarks: Pre-Flush w/ 15 BBLS H20
Displace w/ 23.5 BBLS H20
Circulate 4 BBLS Cement

Tax Reference Code	Sub Total
State CO 2.9 %	Tax
Disc.	Total

Truck No.	Code	State Mileage	Nebraska	Colorado	Wyoming
1208		Pump Truck		31	
1214		Bulk Truck		31	

We do not assume any responsibility for any damage or conditions resulting from our services. All pricing is subj

Delivered By Justin, Steve, Dallas & James

Received By

Customer or His Agent