32-1603

CEMENTER'S WELL SERVICE, INC.

P.O. BOX 336220 • GREELEY, CO 80633 • (970) 353-7299 • FAX (970) 353-7712

OUR INVOICE

199765

Date 5/26/11	Well Owner PDC	Well No. 2040	Lease Ryland
County Weld	State Colorado		Field
Charge to Ensign US Drilling			Charge Code
Address P.O. Box 17505 / Ensign #321			For Office Use Only
City, State Denver Colorado 80217			
Pump Truck No. 1208	Code	Bulk Truck No. 1214	Code
Type of Job		Depth	Ft. 680 To
Surface 375 sks 35/65	24"	Bottom of Surface	Ft. 672 To
Plug		Plug Landed @ 1027 Ft.	Time On 0310
Production		Pipe Landed @ 672 Ft.	Time Off Plug Down 0600

Reference No.	Description	Qty.	Meas.	Unit Price	Amount
	Pump Truck Charge				
	Cement Neat ✓	470	sks		
	Poz. Mix				
	Calcium Chloride	3%			
	Gel % Flo-Cele #Per Sack				
	Handling Charge				
	Hauling Charge				
	Additional Cement				
	Mixed @ Rate - 4 BPM / Displacement - Rate - 4 BPM				
	Slurry Vol - 1.18 cu ft/sk - Slurry Wt 15.8 PPG				
	Total Slurry Vol 98.5 BBLS Cement				
	Landed Plug @ 300 PSI / Water Test				

Remarks: Pre-Flush w/ 20 BBLS H20
Tail-Slurry w/ 40 BBLS H20
Circulate 4 BBLS Cement

Tax Reference Code		Sub Total
State 7.02.9 %		Tax
Disc.		Total

Truck No.	Code	State Mileage	Nebraska	Colorado	Wyoming	
1208		Pump Truck		34		
1214		Bulk Truck		34		

We do not assume any responsibility for any damage or conditions resulting from our services. All pricing is subject to review and revision.

Delivered By Justin Dallas Nebo / Dallas

Received By _____
Customer or His Agent