

DISCLAIMER

THIS MUD LOG IS PROVIDED FOR GENERAL INFORMATION PURPOSES ONLY. WHILE EFFORTS HAVE BEEN MADE TO ENSURE THE ACCURACY OF THE DATA CONTAINED HEREIN, NO WARRANTY, EXPRESS OR IMPLIED, IS MADE REGARDING THE COMPLETENESS, ACCURACY, OR RELIABILITY OF THE INFORMATION. THE INTERPRETATIONS AND CONCLUSIONS PRESENTED ARE BASED ON THE INTERPRETATION OF DRILLING DATA AND MAY NOT REFLECT ACTUAL SUBSURFACE CONDITIONS. USERS SHOULD NOT RELY SOLELY ON THIS MUD LOG FOR DRILLING, COMPLETION, OR PRODUCTION DECISIONS. INDEPENDENT VERIFICATION AND PROFESSIONAL JUDGMENT ARE ESSENTIAL. THE PREPARERS AND DISTRIBUTORS OF THIS MUD LOG SHALL NOT BE LIABLE FOR ANY DIRECT, INDIRECT, INCIDENTAL, OR CONSEQUENTIAL DAMAGES ARISING FROM THE USE OF THIS INFORMATION. BY USING THIS MUD LOG, YOU AGREE TO THESE TERMS AND ACKNOWLEDGE THAT YOU HAVE READ AND UNDERSTOOD THIS DISCLAIMER.

THANKS FOR CHOOSING HALLIBURTON/BAKER HUGHES SERVICES!



HALLIBURTON

MAIN LOG PASS

07:10:00

HALLIBURTON

REPEAT LOG PASS

07:10:00

HALLIBURTON

FREE PIPE SECTION

07:10:00

HALLIBURTON

MAIN LOG PASS

07:10:00

HALLIBURTON

REPEAT LOG PASS

07:10:00

HALLIBURTON

FREE PIPE SECTION

07:10:00

HALLIBURTON

07:10:00

Customer: LUNDIN ENERGY A.G.G.
Well: 16/1-BUCHAN F-20 A ST2
Field: BUCHAN FIELD
Block: 16/1a

Date: 1.0
Survey Type: CASED HOLE LOG
API No.: