CEMENTER'S WELL SERVICE, INC.

P.O. BOX 336220 · GREELEY, CO 80633 · (970) 353-7299 · FAX (970) 353-7712

OUR INVOICE

200388

Po#

Date 2/25/12	Well Owner Bayswater	Well No. 20-31	Lease [redacted]
County Weld	State Colorado		Field
Charge to Ensign U.S. Drilling (Ensign 7)			Charge Code
Address PO Box 17805			For Office Use Only
City, State Denver, Colorado 80217			

Pump Truck No. 1201	Code	Bulk Truck No. 1207/1217	Code		
Type of Job		Depth	Ft. 969		To
(Surface) 8 5/8 CSG	24#	Bottom of Surface	Ft. 955		To
Plug		Plug Landed @ 908	Ft.	Time On 1400	
Production		Pipe Landed @ 955	Ft.	~~Time Off~~ Plug Down 2145	

Reference No.	Description	Qty.	Meas.	Unit Price	Amount
	Pump Truck Charge				
	Cement Neat ✓	670	SKS		[redacted]
	Poz. Mix				
	Calcium Chloride	3%			
	Gel % Flo-Cele 1/4 #Per Sack				
	Handling Charge				
	Hauling Charge				
	Additional Cement				

Mix Rate 4 Bpm / Disp Rate 5 Bpm
Slurry Vol 1.18 CUFT3/SK Slurry wt. 14.8-15 PPG
Total Slurry Vol 168 BBL cement / Plug landed @ 750 PSI

Remarks: Pre-Flush w/20 BBL H2O	Tax Reference Code	Sub Total	[redacted]
Displace w/57.7 BBL H2O	State CO 2.9 %	Tax	
Circulate 7 BBL Cement	Disc.	Total	[redacted]

Truck No.	Code	State Mileage	Nebraska	Colorado	Wyoming	Other	Total Mileage
1201		Pump Truck		28			
1207/1217		Bulk Truck		28/28			

We do not assume any responsibility for any damage or conditions resulting from our services. All pricing is subject to review and revision.

Delivered By Jim, Adam, Jason, Joe

Received By _____
Customer or His Agent