Click here to reset form

FORM 22 Rev 6/99

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 (303) 894-2100 Fax: (303) 894-2109

FOR OGCC USE ONLY

Report taken by:

ACCIDENT REPORT

As required by Rule 602.b.

DESCRIPTION OF ACCIDENT (Please be as specific as possible)

Name of Operator: PDC Energy
Date of Incident: 2/11/2013
Type of Facility (well, tank battery, flow line, pit): Well
Well Name and Number: Ochsner 5O-441
API Number: 05-123-36153
Connect to Accident (land owner, royalty owner, etc).: Doug Ochsner

Location

County: Weld
Field Name: Wattenberg
QtrQtr: SENW Section: 5
Township: 6N Range: 67W
Meridian: 6th

Provide a detailed description of the accident, problem, and cause (equipment failure, human error, etc.):

Workover Rig was rigging up to snub production tubing in the well and had begun to lift the operator stand and set it in position on the derrick. While attempting to set the pins of the stand, the rig lost air which caused the blocks to slowly descend (Approx 30 feet) and strike the wellhead breaking the master valve handle and shearing one of the tubing hanger locking pins. The shearing of the tubing hanger lock pin caused the pressurized wellhead to begin flowing through the broken lock pin hole on the wellhead below the master valve. There was 800 psi on the wellhead at the time and no other valve or means existing to shut the well in and regain immediate control of flowback fluids. A review of the rig equipment failure was underway, but no information of the findings was available for this report.

OTHER NOTIFICATIONS

List the parties and agencies notified (County, BLM, EPA, DOT, Local Emergency Planning Coordinator or other).

Date	Agency	Contact Person	Response
2/11/2013	COGCC	Diana Burn/ 303-894-5106	
2/11/2013	CDPHE/APCD	Jennifer Mattox	
2/11/2013	CDPHE/APCD	Mark McMillan	Left Message
2/11/2013	Landowner	Doug Ochsner	Onsite Consultation
2/11/2013	COGCC	Bob Chesson	

Accident Tracking No:_____