
Schlumberger
Mud Log
Quadrant
Well Name
Field
County
State
Location
Elevation
Permanent Datum
Log Measured From
Drilling Measured From
Date
Run Number
Depth Driller
Depth Logger
Bottom Logged Interval
Top Logged Interval
Type Fluid in Hole
Salinity
Density
Viscosity
Ph
Fluid Loss
Source of Sample
Rm @ Measured Temp
Rmf @ Measured Temp
Rmc @ Measured Temp
Source of Rmf and Rmc
Rm @ BHT
Time Circulation Stopped
Time Logger on Bottom
Max Recorded Temperature
Equipment Number
Location
Recorded By
Witnessed By
Run No.
Bit No.
Type
Size
From
To
Hrs
Total Depth
Weight
Viscosity
Pump Pressure
Flow Rate
Type
Size
Make
Model
Serial No.
Top
Bottom
Type
Density
Viscosity
Ph
Fluid Loss
Source
Rm @ Measured Temp
Rmf @ Measured Temp
Rmc @ Measured Temp
Source of Rmf and Rmc
Rm @ BHT
Max Recorded Temperature
Circulation Stopped
Logger on Bottom
Logging Unit Number
Logging Engineer



Company: AGRA EARTH & ENVIRONMENTAL
Client: Pioneer
Field: Not Entered
Structure: #01
Well: #01
Country: US

Location: SEC 35 T1S R1E
Service Co.: Weatherford
Job Type: Cased Hole
Job Number: 1
Date: 10/19/2010
Time: 10:00:00 AM
Unit Number: 3
Engineer: Jeff Hall
Witness: Jeff Hall
Weather: Clear
Temperature: 70 F
Remarks: Initial Baseline Survey

Equipment Used: Gamma Ray and Neutron Tools

Log Interval: 1,000 ft
Pipe Type: Casing
Pipe Weight: 17 lbs/ft
Pipe Grade: J-55
Fluid Level: Dry
Max Recorded Temperature: 70 F
Equipment Number: 1
Max Recorded Deviation: 0 deg
Recorded By: Jeff Hall
Witnessed By: Jeff Hall

Gamma Calibration: Calibrated Before Run 1 - 10:00:00 AM

Run 1
Start: 1,000 ft
Stop: 0 ft
Speed: 30 ft/min
Log Direction: Down

Calibration 1
Start: 1,000
Stop: 1,000
Shift: 0
Time: 10:00:00 AM

Run 2
Start: 0 ft
Stop: 1,000 ft
Speed: 30 ft/min
Log Direction: Up

Calibration 2
Start: 1,000
Stop: 1,000
Shift: 0
Time: 10:30:00 AM

Neutron Calibration: Calibrated Before Run 1 - 10:00:00 AM

Run 1
Start: 1,000 ft
Stop: 0 ft
Speed: 30 ft/min
Log Direction: Down

Calibration 1
Start: 1,000
Stop: 1,000
Shift: 0
Time: 10:00:00 AM

Run 2
Start: 0 ft
Stop: 1,000 ft
Speed: 30 ft/min
Log Direction: Up

Calibration 2
Start: 1,000
Stop: 1,000
Shift: 0
Time: 10:30:00 AM

Tool Information

Gamma Ray Tool: 1
Serial Number: 10001
Detector: NaI(Tl) 1.5" x 12"
Offset: 0 ft

Neutron Tool: 1
Serial Number: 10001
Source: Am-241/Be 5 Ci
Offset: 0 ft

Tool Combination: Gamma Ray + Neutron
Total Tool Length: 12 ft
Centralizers: Yes
Decentralizers: No

Log Quality: Good
Repeatability: Verified
Depth Control: Wireline Counter
Casing Collars: Logged
Perforations: None
Anomalies: None

Operator Witness: Jeff Hall
Witness Signature: _____
Date: 10/19/2010

Prepared by: Jeff Hall
Date: 10/19/2010
Time: 10:00:00 AM

PIONEER
Pioneer Natural Resources