
MAIN PASS
MAIN PASS
MAIN PASS

PIONEER

REPEAT SECTION

Calibration Run: 2008-01-09
Calibration Time: 10:30:00
Calibration Depth: 0 m
Calibration Location: 30°16.00' N 97°45.00' W (or NAD 1983)

TX	CORE SAMPLER	RX	MAP DRIFT CYCLE (DC)
Starting Point (SOH)	0 m	Starting Point (SOH)	0 m

Calibration Report

Calibration Run: 2008-01-09
Calibration Time: 10:30:00
Calibration Depth: 0 m
Calibration Location: 30°16.00' N 97°45.00' W (or NAD 1983)

Serial Number	1234-5678
Firmware Version	1.0.3
Firmware Date	2007-11-15 10:22:45 (EST)
Calibration Status	Pass
Number of Points	13
Number Passed	13
Number Failed	0

Superimposed Actual Curve and Calibration Report

Serial Number	1234-5678
Firmware Version	1.0.3
Calibration Actual Number	1 of 1
Calibration Status	Pass

Repeat Calibration performed on 2008-01-09 10:37:00 (EST)

Test 1A			Calibration Curve		Results	
Time	Ch1	Ch2	Time	Ch1	Ch1	Ch2
0	0.000	0.000	0	0.000	0.000	0.000
1	0.000	0.750	1.000	0.750	0.000	0.750
2	0.000	1.500	2.000	1.500	0.000	1.500
3	0.000	2.250	3.000	2.250	0.000	2.250
4	0.000	3.000	4.000	3.000	0.000	3.000
5	0.000	3.750	5.000	3.750	0.000	3.750
6	0.000	4.500	6.000	4.500	0.000	4.500
7	0.000	5.250	7.000	5.250	0.000	5.250
8	0.000	6.000	8.000	6.000	0.000	6.000
9	0.000	6.750	9.000	6.750	0.000	6.750
10	0.000	7.500	10.000	7.500	0.000	7.500
11	0.000	8.250	11.000	8.250	0.000	8.250
12	0.000	9.000	12.000	9.000	0.000	9.000

Manual Calibration performed on 2008-01-09 10:37:00 (EST)

Test 1A			Calibration Curve		Results	
Time	Ch1	Ch2	Time	Ch1	Ch1	Ch2
0	0.000	0.000	0	0.000	0.000	0.000
1	0.000	0.750	1.000	0.750	0.000	0.750
2	0.000	1.500	2.000	1.500	0.000	1.500
3	0.000	2.250	3.000	2.250	0.000	2.250
4	0.000	3.000	4.000	3.000	0.000	3.000
5	0.000	3.750	5.000	3.750	0.000	3.750
6	0.000	4.500	6.000	4.500	0.000	4.500
7	0.000	5.250	7.000	5.250	0.000	5.250
8	0.000	6.000	8.000	6.000	0.000	6.000
9	0.000	6.750	9.000	6.750	0.000	6.750
10	0.000	7.500	10.000	7.500	0.000	7.500
11	0.000	8.250	11.000	8.250	0.000	8.250
12	0.000	9.000	12.000	9.000	0.000	9.000

PIONEER
Pioneer Drilling Services, Ltd.
Copyright Notice: ©2008
Author: Jason Lee Scott (EST)
Phone: 555-555-0123
Email: jason@pioneer.com
Fax: 555-555-0124