FORM INSP Rev X/15	State of Colorado Oil and Gas Conservation Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109 **FIELD INSPECTION FORM**	DNR CO	Inspection Date: 12/05/2016 Submitted Date: 12/16/2016 Document Number: 666802826

Loc ID 323837

Inspector Name: Murray, Richard

On-Site Inspection ☐

2A Doc Num:

Status Summary:

☐ THIS IS A FOLLOW UP INSPECTION

☐ FOLLOW UP INSPECTION REQUIRED

☒ NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100185

Name of Operator: ENCANA OIL & GAS (USA) INC

Address: 370 17TH ST STE 1700

City: DENVER   State: CO   Zip: 80202-

Findings:

2 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210931	WELL	PR	10/28/2005	GW	045-06689	MAMM CREEK RANCH T45-20P (K20E)	PR

General Comment:

Inspection is to witness Plug and abandoned well

Inspected Facilities					
Facility ID: 210931	Type: WELL	API Number: 045-06689	Status: PR	Insp. Status: PR	

Cement

Cement Contractor

    Contractor Name: _____   Contractor Phone: _____

Surface Casing

    Cement Volume (sx): _____   Circulate to Surface: _____

    Cement Fall Back: _____   Top Job, 1" Volume: _____

Intermediate Casing

    Cement Volume (sxs): _____   Good Return During Job: _____

Production Casing

    Cement Volume (sx): _____   Good Return During Job: _____

Plugging Operations

    Depth Plugs(feet range): 4197 _____   Cement Volume (sx): 20

Good Return During Job: _____   Cement Type: Class G

Comment: Mix and pump- Total of 20sks (4 Bbls.) of 15.8# 1.15 Cu,Ft./sk Class G cement. (100gal of fresh water added to Cement slurry mix)- Spot 20sks (4bbls.) of cement on top of CIBP (set @ 4197') Pumped 15.5 Bbls. of fresh water displacement down tbg, (Puts 108 ft. of cement on top CIBP, Est cement top @ 4089')

Corrective Action: _____   Date: