Cutters Wireline Service, Inc.
A Cased Hole Wireline Company

40 Arm Caliper
Gamma Ray
CCL Log

Company Chevron
Well Fee 143X
Field Rangley
County Rio Blanco
State Co

Company	Chevron		
Well	Fee 143X		
Field	Rangley		
County	Rio Blanco	State	Co

Location:
API # :
SEC TWP RGE

Other Services

Permanent Datum
Elevation
Log Measured From
Drilling Measured From

Elevation
K.B.
D.F.
G.L.

Date	23-Aug-2017		
Run Number	One		
Depth Driller			
Depth Logger	3171		
Bottom Logged Interval	3171		
Top Log Interval	Surface		
Open Hole Size			
Type Fluid	Water		
Density / Viscosity			
Max. Recorded Temp.			
Estimated Cement Top			
Time Well Ready			
Time Logger on Bottom			
Equipment Number	135		
Location	Vernal		
Recorded By	Eric Atwood		
Witnessed By			

Borehole Record				Tubing Record			
Run Number	Bit	From	To	Size	Weight	From	To

Casing Record	Size	Wgt/Ft	Top	Bottom
Surface String				
Prot. String				
Production String				
Liner				

<<< Fold Here >>>

All interpretations are opinions based on inferences from electrical or other measurements and we cannot and do not guarantee the accuracy or correctness of any interpretation, and we shall not, except in the case of gross or willful negligence on our part, be liable or responsible for any loss, costs, damages, or expenses incurred or sustained by anyone resulting from any interpretation made by any of our officers, agents or employees. These interpretations are also subject to our general terms and conditions set out in our current Price Schedule.

Comments

Cutters®
Wireline Service, Inc.
A Cased Hole Wireline Company

Main Pass

Database File: fee143x.db
Dataset Pathname: pass5
Presentation Format: msc55gr
Dataset Creation: Wed Aug 23 12:55:20 2017 by Log SCH 120430
Charted by: Depth in Feet scaled 1:240

Gamma Ray	Casing Image	Nominal Thickness	Average ID	1.875 R10 (in) 4.375
0 (GAPI) 150		0 (in) 1	3.5 (in) 5.25	1.25 R20 (in) 3.75
9 Casing Collars -1		Minimum Thickness	Maximum ID	0.625 R30 (in) 3.125
		0 (in) 1	5.25 (in) 3.5	0 R40 (in) 2.5
		Maximum Thickness	Minimum ID	
		0 (in) 1	3.5 (in) 5.25	
		Average Thickness	Nominal ID	
		0 (in) 1	5.25 (in) 3.5	
		AVTK (in)	IDAV (in)	

































Gamma Ray	Casing Image	Nominal Thickness	Average ID	1.875 R10 (in) 4.375
0 (GAPI) 150		0 (in) 1	3.5 (in) 5.25	1.25 R20 (in) 3.75
9 Casing Collars -1		Minimum Thickness	Maximum ID	0.625 R30 (in) 3.125
		0 (in) 1	5.25 (in) 3.5	0 R40 (in) 2.5
		Maximum Thickness	Minimum ID	
		0 (in) 1	3.5 (in) 5.25	
		Average Thickness	Nominal ID	
		0 (in) 1	5.25 (in) 3.5	
		AVTK (in)	IDAV (in)	

Cutters
Wireline Service, Inc.
A Cased Hole Wireline Company

Repeat Pass

Database File: fee143x.db
Dataset Pathname: pass4
Presentation Format: msc55gr
Dataset Creation: Wed Aug 23 12:45:10 2017 by Log SCH 120430
Charted by: Depth in Feet scaled 1:240

Gamma Ray	Casing Image	Nominal Thickness	Average ID	1.875 R10 (in) 4.375
0 (GAPI) 150		0 (in) 1	3.5 (in) 5.25	1.25 R20 (in) 3.75
9 Casing Collars -1		Minimum Thickness	Maximum ID	0.625 R30 (in) 3.125
		0 (in) 1	5.25 (in) 3.5	0 R40 (in) 2.5
		Maximum Thickness	Minimum ID	
		0 (in) 1	3.5 (in) 5.25	
		Average Thickness	Nominal ID	
		0 (in) 1	5.25 (in) 3.5	
		AVTK (in)	IDAV (in)	



0 (in) 1	5.25 (in) 3.5	0 R40 (in) 2.5
Maximum Thickness	Minimum ID	
0 (in) 1	3.5 (in) 5.25	
Average Thickness	Nominal ID	
0 (in) 1	5.25 (in) 3.5	
AVTK (in)	IDAV (in)	

Sensor	Offset (ft)	Schematic	Description	Len (ft)	OD (in)	Wt (lb)
			CHD-STNDRD (1) Standard Cable Head	1.00	1.69	10.00
			Titan 2 3/4" Titan large bow spring centralizer	2.92	2.75	15.00
CCL DCCL GR	13.50 13.50 12.00		GR-GCT_C3 (FW1304-53) Probe Digital Gamma CCL Corrosion	4.77	2.75	50.00
			Titan 2 3/4" Titan large bow spring centralizer	2.92	2.75	15.00



Probe_MFCAL-40 (FW1302-15) Probe 40 Arm Caliper	6.67	2.81

Meas	1.00
ETemp	1.00
ACCX	0.00
ACCY	0.00
ACCZ	0.00

Dataset:	fee143x.db: field/well/run1/pass5
Total Length:	18.27 ft
Total Weight:	90.00 lb
O.D.	2.81 in