
Mud Logging Services
Gas Ratio Curves
Lithology
Drilling Rate
Gas Units
Chromatography (PPM)
Lithology Descriptions
Sample Quality
Shows
Oil Stain
Fluorescence
Cut
Residual Cut
Cut Fluorescence
Total Gas
Connection Gas
Trip Gas
Background Gas
Chromatography





Prepared Pipes
Reinstated RMS-STD Surface Induced Pressure
Reinstated RMS-STD Surface Induced Pressure
Reinstated RMS-STD Surface Induced Pressure