FORM INSP Rev X/15	State of Colorado Oil and Gas Conservation Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109 **FIELD INSPECTION FORM**	DNR CO	Inspection Date: 04/01/2019 Submitted Date: 04/01/2019 Document Number: 695100409

Loc ID	Inspector Name:	On-Site Inspection ☐
309220	Beardslee, Tom	2A Doc Num:

Operator Information:

OGCC Operator Number: 10084

Name of Operator: PIONEER NATURAL RESOURCES USA INC

Address: 5205 N O'CONNOR BLVD STE 200

City: IRVING   State: TX   Zip: 75039

Status Summary:

☐ THIS IS A FOLLOW UP INSPECTION

☒ FOLLOW UP INSPECTION REQUIRED

☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7   Number of Comments

2   Number of Corrective Actions

☒ Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Distribution, Pioneer	972-444-9001	COGCC.Inspections@pxd.com	All Inspections
Distribution, Evergreen		cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290293	WELL	PR	08/10/2007	GW	071-09259	SPINACH 43-8	PR

General Comment:

Inspector Name: Beardslee, Tom

Location			
Overall Good: ☒			

Signs/Marker:

Type	OTHER		
Comment:	WELL SIGN ON METER HOUSE		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	
Corrective Action:	Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	HYDRAULIC HOSES APPEAR TO BE SEEPING HYDRAULIC FLUID. HOSES ARE WET WITH HYDRAULIC FLUID		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	05/01/2019
Type	OTHER		
Comment:	IMPACTED SOIL FROM HYDRAULIC LEAK IMPACTED SOIL NEAR WELLHEAD		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A.	Date:	05/01/2019

Overall Good: ☐

Spills:

Type	Area	Volume			

In Containment: No

Comment:	

☐ Multilple Spills and Releases?

Equipment:				corrective date
Type: Ancillary equipment	# 1			
Comment:	TELEMETRY EQUIPMENT			
Corrective Action:			Date:	
Type: Other	# 1			
Comment:	BREADENHEAD IS PLUMBED TO SURFACE			
Corrective Action:			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		

Inspector Name: Beardslee, Tom

Corrective Action:		Date:	

Inspected Facilities							
Facility ID:	290293	Type:	WELL	API Number:	071-09259	Status:	PR	Insp. Status:	PR

Producing Well

Comment:	
Corrective Action:	Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: _____

Corrective Action: _____ Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:

Document Num	Description	URL
401992252	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4780762
695100410	LOCATION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4780757