



Complaint 200095595



Photograph 1: Depression on Baros Property, view is south.



Photograph 2: View of drilling mud not removed by the property owner, view is east.



Map Source: USGS, 2002

LEGEND

- BACKGROUND SAMPLE
- NOBLE SAMPLE
- TEXAS AMERICA SAMPLE
- BAROS RESIDENCE
- DEPRESSION
- - - PROPERTY BOUNDARY
- APPLIED DRILLING MUD
- REMOVED DRILLING MUD




FIGURE 1
SAMPLING LOCATIONS AND PROPERTY MAP
BAROS PROPERTY
ADAMS COUNTY, COLORADO

NOBLE ENERGY, INC.





Photograph 7: Drilling mud applied by the property owner to the edge of the driveway, view is west.




Photograph 5: Application of removed drilling mud along the driveway, view is east.



Photograph 6: Drilling mud applied by the property owner to the front yard, view is south east.



Photograph 3: Noble contractors removing drilling mud, view is north.



Photograph 4: Soil sample location for Sample N-2.

ATTACHMENT A
SITE PHOTOGRAPHS

