

Form 9-331
(May 1963)

DEP/



99999999

GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

Colorado 0682

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Thornburg Unit

8. FARM OR LEASE NAME

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Thornburg Water
11. SEC. T. R. M. OR BLK. AND
SURVEY OR AREA

Sec. 8, T. 34N, R. 91W, 6th PM
12. COUNTY OR PARISH 13. STATE

Moffat

Colorado

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ P&A

2. NAME OF OPERATOR

Continental Oil Company

3. ADDRESS OF OPERATOR

P. O. Box 1621, Durango, Colorado

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

330' FSL, 1650' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well is non-commercial and was plugged and abandoned in October, 1965, as follows: Filled hole with heavy mud. Run 10 sack plug across perforations 4250'-4320'. Cut and pulled 1000' of 7" casing. Run 10 sack plug across stub at 1000'. Run 10 sack plug at surface shoe, 146'-166'. Run 10 sack plug at surface, erected regulation marker and cleaned location. P & A completed 10/3/65.

DVR	
WRS	
HHM	
JAM	✓
FJP	✓
JJD	✓
FILE	

18. I hereby certify that the foregoing is true and correct

SIGNED ORIGINAL SIGNED BY:

BEN W. SMITH

TITLE Assistant District Manager

DATE 11-1-65

(This space for Federal or State office use)

APPROVED BY *W. Rogers*
CONDITIONS OF APPROVAL IF ANY:

TITLE Director

DATE NOV 12 1965

OIL & GAS COMM

USGS(3) CO&GCC(2) Sincla



00643763

on Reverse Side