

FORM
2
Rev
12/05

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

APPLICATION FOR PERMIT TO:

1. Drill, Deepen, Re-enter, Recomplete and Operate

2. TYPE OF WELL

OIL GAS COALBED OTHER _____
SINGLE ZONE MULTIPLE ZONE COMMINGLE ZONE

Refiling
Sidetrack

Document Number:
400082227
Plugging Bond Surety
20100017

3. Name of Operator: ENCANA OIL & GAS (USA) INC 4. COGCC Operator Number: 100185

5. Address: 370 17TH ST STE 1700
City: DENVER State: CO Zip: 80202-5632

6. Contact Name: Julia Carter Phone: (720)876.5240 Fax: (720)876.6240
Email: Julia.Carter@encana.com

7. Well Name: Kimball Mtn Well Number: DH01-6 B07 799

8. Unit Name (if appl): _____ Unit Number: _____

9. Proposed Total Measured Depth: 13264

WELL LOCATION INFORMATION

10. QtrQtr: NWNE Sec: 7 Twp: 7S Rng: 99W Meridian: 6
Latitude: 39.467811 Longitude: -108.481997

Footage at Surface: 98 FNL/FSL FNL 1868 FEL/FWL FEL

11. Field Name: Gasaway Field Number: 29560

12. Ground Elevation: 6649 13. County: GARFIELD

14. GPS Data:

Date of Measurement: 03/02/2010 PDOP Reading: 1.9 Instrument Operator's Name: Robert Kay

15. If well is Directional Horizontal (highly deviated) **submit deviated drilling plan.**

Footage at Top of Prod Zone: FNL/FSL 12 FNL 195 FEL FEL Bottom Hole: FNL/FSL 1 FNL 195 FEL FEL
Sec: 7 Twp: 7S Rng: 99W Sec: 6 Twp: 7S Rng: 99W

16. Is location in a high density area? (Rule 603b)? Yes No

17. Distance to the nearest building, public road, above ground utility or railroad: 1368 ft

18. Distance to nearest property line: 1222 ft 19. Distance to nearest well permitted/completed in the same formation: 1400 ft

20. LEASE, SPACING AND POOLING INFORMATION

Objective Formation(s)	Formation Code	Spacing Order Number(s)	Unit Acreage Assigned to Well	Unit Configuration (N/2, SE/4, etc.)
Mancos	MNCS			

21. Mineral Ownership: Fee State Federal Indian Lease #: _____

22. Surface Ownership: Fee State Federal Indian

23. Is the Surface Owner also the Mineral Owner? Yes No Surface Surety ID#: _____

23a. If 23 is Yes: Is the Surface Owner(s) signature on the lease? Yes No

23b. If 23 is No Surface Owners Agreement Attached or \$25,000 Blanket Surface Bon \$2,000 Surface Bond \$5,000 Surface Bond

24. Using standard QtrQtr, Sec, Twp, Rng format enter entire mineral lease description upon which this proposed wellsite is located (attach separate sheet/map if you prefer):
Please see attached maps

25. Distance to Nearest Mineral Lease Line: 4881 ft 26. Total Acres in Lease: 10278

DRILLING PLANS AND PROCEDURES

27. Is H2S anticipated? Yes No If Yes, attach contingency plan.

28. Will salt sections be encountered during drilling? Yes No

29. Will salt (>15,000 ppm TDS CL) or oil based muds be used during drilling? Yes No

30. If questions 27 or 28 are yes, is this location in a sensitive area (Rule 903)? Yes No **If 28, 29, or 30 are "Yes" a pit permit may be required.**

31. Mud disposal: Offsite Onsite

Method: Land Farming Land Spreading Disposal Facility Other: Recycle & Bury

Note: The use of an earthen pit for Recompletion fluids requires a pit permit (Rule 905b). If air/gas drilling, notify local fire officials.

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bottom	Cement Top
CONDUCTOR	30	20	Line Pipe	120	319	120	0
SURF	13+1/2	10+3/4	40.5	1,800	513	1,800	0
1ST	9+7/8	7+5/8	29.7	6,771	431	6,771	2,756
2ND	6+1/2	4+1/2	13.5	13,264	507	13,264	6,571

32. BOP Equipment Type: Annular Preventer Double Ram Rotating Head None

33. Comments Please note that Intermediate casing is listed as 'first string' and Production casing is listed as 'second string'. The distance on #17 is calculated from Kimball Creek Rd.

34. Location ID: 383216

35. Is this application in a Comprehensive Drilling Plan ? Yes No

36. Is this application part of submitted Oil and Gas Location Assessment ? Yes No

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Julia M. Carter

Title: Regulatory Analyst Date: 8/5/2010 Email: Julia.Carter@encana.com

Based on the information provided herein, this Application for Permit-to-Drill complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: David S. Neslin Director of COGCC Date: 9/20/2010

API NUMBER
05 045 19929 00

Permit Number: _____ Expiration Date: 9/19/2012

CONDITIONS OF APPROVAL, IF ANY: _____

All representations, stipulations and conditions of approval stated in the Form 2A for this location shall constitute representations, stipulations and conditions of approval for this Form 2 Permit-to-Drill and are enforceable to the same extent as all other representations, stipulations and conditions of approval stated in this Permit-to-Drill.

- 1) COMPLIANCE WITH THE MOST CURRENT REVISION OF THE NORTHWEST COLORADO NOTIFICATION POLICY IS REQUIRED.
- 2) GARFIELD COUNTY RULISON FIELD NOTICE TO OPERATORS. NOTE: ALL NOTICES SHALL BE GIVEN VIA E-MAIL. SEE ATTACHED NOTICE
- 3) INTERMEDIATE CASING CEMENT TOP VERIFICATION BY CBL REQUIRED.
- 4) THE PROPOSED SURFACE CASING IS MORE THAN 50' BELOW THE DEPTH OF THE DEEPEST WATER WELL WITHIN 1 MILE OF THE SURFACE LOCATION WHEN CORRECTED FOR ELEVATION DIFFERENCES. THE DEEPEST WATER WELL WITHIN 1 MILE IS 000 FEET DEEP.

Attachment Check List

Att Doc Num	Name	Doc Description
400082227	FORM 2 SUBMITTED	LF@2519519 400082227
400082661	PLAT	LF@2519520 400082661
400082662	DEVIATED DRILLING PLAN	LF@2519521 400082662
400082663	TOPO MAP	LF@2519522 400082663
400082664	LEASE MAP	LF@2519523 400082664
400082665	OTHER	LF@2519524 400082665

Total Attach: 6 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Permit	Received clarification on survey plat and verified data. Ready to process BY 9/17/10	9/17/2010 9:32:42 AM
Permit	WO on information from operator. Discrepancies between surveyor's lat/long numbers and their spotting on plat for the APD'. There appears to be intermittent stream within 120' (east) of the locations.	9/10/2010 12:34:00 PM

Total: 2 comment(s)

Error: Subreport could not be shown.