

FORM
2

Rev
12/05

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

APPLICATION FOR PERMIT TO:

1. Drill, Deepen, Re-enter, Recomplete and Operate

2. TYPE OF WELL

OIL GAS COALBED OTHER _____
SINGLE ZONE MULTIPLE ZONE COMMINGLE ZONE

Refiling

Sidetrack

Document Number:

400093184

Plugging Bond Surety

20090040

3. Name of Operator: FRAM OPERATING LLC

4. COGCC Operator Number: 10310

5. Address: 30 E PIKES PEAK AVE STE 283

City: COLORADO State: CO Zip: 80903
SPRINGS

6. Contact Name: David Cook Phone: (719)355-1320 Fax: (719)314-1362

Email: dave@framamericas.com

7. Well Name: Siminoe Well Number: 32-2-1

8. Unit Name (if appl): Whitewater Unit Number: 73038X

9. Proposed Total Measured Depth: 2900

WELL LOCATION INFORMATION

10. QtrQtr: 11 Sec: 32 Twp: 12S Rng: 97W Meridian: 6

Latitude: 38.961760 Longitude: -108.265970

Footage at Surface: 1868 FNL/FSL FSL 709 FEL/FWL FWL

11. Field Name: Wildcat Field Number: 99999

12. Ground Elevation: 5784 13. County: MESA

14. GPS Data:

Date of Measurement: 06/03/2005 PDOP Reading: 6.0 Instrument Operator's Name: Jeff Fletcher

15. If well is Directional Horizontal (highly deviated) **submit deviated drilling plan.**

Footage at Top of Prod Zone: FNL/FSL 876 FSL 1118 FWL 1873 FEL/FWL 1937 FWL FWL

Sec: 32 Twp: 12S Rng: 97W Sec: 32 Twp: 12S Rng: 97W

16. Is location in a high density area? (Rule 603b)? Yes No

17. Distance to the nearest building, public road, above ground utility or railroad: 545 ft

18. Distance to nearest property line: 656 ft 19. Distance to nearest well permitted/completed in the same formation: 1225 ft

20. LEASE, SPACING AND POOLING INFORMATION

Objective Formation(s)	Formation Code	Spacing Order Number(s)	Unit Acreage Assigned to Well	Unit Configuration (N/2, SE/4, etc.)
Dakota	DKTA	376-1	320	W/2

21. Mineral Ownership: Fee State Federal Indian Lease #: _____

22. Surface Ownership: Fee State Federal Indian

23. Is the Surface Owner also the Mineral Owner? Yes No Surface Surety ID#: _____

23a. If 23 is Yes: Is the Surface Owner(s) signature on the lease? Yes No

23b. If 23 is No Surface Owners Agreement Attached or \$25,000 Blanket Surface Bon \$2,000 Surface Bond \$5,000 Surface Bond

24. Using standard QtrQtr, Sec, Twp, Rng format enter entire mineral lease description upon which this proposed wellsite is located (attach separate sheet/map if you prefer):
SEE ATTACHED.

25. Distance to Nearest Mineral Lease Line: 700 ft 26. Total Acres in Lease: 107

DRILLING PLANS AND PROCEDURES

27. Is H2S anticipated? Yes No If Yes, attach contingency plan.

28. Will salt sections be encountered during drilling? Yes No

29. Will salt (>15,000 ppm TDS CL) or oil based muds be used during drilling? Yes No

30. If questions 27 or 28 are yes, is this location in a sensitive area (Rule 903)? Yes No **If 28, 29, or 30 are "Yes" a pit permit may be required.**

31. Mud disposal: Offsite Onsite

Method: Land Farming Land Spreading Disposal Facility Other: Using a closed loop system

Note: The use of an earthen pit for Recompletion fluids requires a pit permit (Rule 905b). If air/gas drilling, notify local fire officials.

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bottom	Cement Top
CONDUCTOR	16	14		40	4	40	
SURF	12+1/4	9+5/8	36	500	110	500	
2ND	8+3/4	5+1/2	17#	4,700	230	4,700	1,800
			Stage Tool	900	50	900	

32. BOP Equipment Type: Annular Preventer Double Ram Rotating Head None

33. Comments The pad is built, pits constructed, this refile will not require an expansion/additional surface disturbance. The location does not require a variance of the rules listed in 306.d(1).(A).(ii) and the location is not in a wildlife restricted occupancy area. No Form 2A required. New 30-day notice letter mailed 9/3/10.

34. Location ID: 334481

35. Is this application in a Comprehensive Drilling Plan ? Yes No

36. Is this application part of submitted Oil and Gas Location Assessment ? Yes No

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: David Cook

Title: Manager Date: 9/15/2010 Email: dave@framamericas.com

Based on the information provided herein, this Application for Permit-to-Drill complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: David S. Nesline Director of COGCC Date: 10/19/2010

API NUMBER: **05 077 09325 00** Permit Number: _____ Expiration Date: 10/18/2012

CONDITIONS OF APPROVAL, IF ANY:

All representations, stipulations and conditions of approval stated in the Form 2A for this location shall constitute representations, stipulations and conditions of approval for this Form 2 Permit-to-Drill and are enforceable to the same extent as all other representations, stipulations and conditions of approval stated in this Permit-to-Drill.

- 1.COMPLIANCE WITH THE MOST CURRENT REVISION OF THE NORTHWEST COLORADO NOTIFICATION POLICY IS REQUIRED.
- 2.THE PROPOSED SURFACE CASING IS MORE THAN 50' BELOW THE DEPTH OF THE DEEPEST WATER WELL WITHIN 1MILE OF THE SURFACE LOCATION WHEN CORRECTED FOR ELEVATION DIFFERENCES. THE DEEPEST WATER WELL WITHIN 1 MILE IS 120 FEET DEEP.
- 3.PRODUCTION CASING CEMENT TOP VERIFICATION BY CBL REQUIRED.
- 4.THE OPERATOR SHALL COMPLY WITH RULE 321. AND IT SHALL BE THE OPERATOR'S RESPONSIBILITY TO ENSURE THAT THE WELLBORE COMPLIES WITH SETBACK REQUIREMENTS IN COMMISSION ORDERS OR RULES PRIOR TO PRODUCING THE WELL.

Attachment Check List

Att Doc Num	Name	Doc Description
400093184	FORM 2 SUBMITTED	LF@2544280 400093184
400093186	30 DAY NOTICE LETTER	LF@2544281 400093186

Total Attach: 2 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Permit	Changed distance to nearest well from 30' to 1225'. Added sec/twn/rng for top of zone & bottom hole. Corrected location number from 10 to 334481 and added spacing order Number 376-1. Changed lat/longs to match change of location sundry dated 12/5/07.	10/15/2010 10:01:49 AM
Permit	400093184--Push back to draft status incorrect Lat. Long., incorrect API, and QtrQtr instead of Lot # for location info	9/16/2010 4:59:30 PM

Total: 2 comment(s)

Error: Subreport could not be shown.