



02054865

Andrews, David

From: Dane_Geyer@blm.gov
Sent: Friday, July 02, 2010 5:04 PM
To: Andrews, David
Cc: Karen_Conrath@blm.gov
Subject: Jolly KP 323-8 (KP 43-8 Pad) surrounding well cement plans.

Follow Up Flag: Follow up
Flag Status: Flagged

045-19052

David, Karen and I have evaluated the Jolly KP 323-8, NESE sec. 8 T6S R91W. From the KP SWD #9-12D OHL (shares the same pad), we have found multiple water zones. One particularly of interest is at about 2800'. We will be requiring cement to be brought up into the surface casing shoe for our federal well, and thought it would be worthwhile to give you a heads-up since multiple fee wells have APDs on the same pad.

Thanks,

Dane Geyer
Petroleum Engineer
Glenwood Springs Field Office in Silt
Bureau of Land Management
PH: 970-876-9048
Cell: 970-589-6887
Fax: 970-876-9090