

**HRM RESOURCES LLC**  
555 17<sup>th</sup> Street, Suite #950  
Denver CO 80202  
(o) 303-893-6621 (f) 303-893-6892

---

2/24/11

Colorado Oil and Gas Conservation Commission  
Attn: David Neslin, Director  
1120 Lincoln Street, Suite 801  
Denver, CO 80203

RE: Rule 318.A.a Exception Location Request  
Rule 318.A.c Exception Location Request

Fritzler Pad - SW NW, Section 21-T6N-R66W  
Fritzler #0-2-21 - 1706' FNL & 518' FWL (Directional)  
Fritzler #12-21 - 1707' FNL & 543' FWL (Vertical)  
Fritzler #2-2-21 - 1706' FNL & 559' FWL (Directional)

Dear Mr. Neslin,

HRM Resources, LLC respectfully requests that the Director grant an exception to Rule 318.A for the above wells. These wells are spotted as above, on a single site and in accordance with the wishes of the surface owner, in order to maximize future land use possibilities and minimize surface disturbance. Per COGCC Rule 318.A(a), a GWA well surface location must be within a 400' by 400' drilling window centered at the center of each quarter-quarter section, or inside a 800' by 800' drilling window centered at the center of each quarter section, or per rule 318.A(c) shall not be less than 50' from an existing well. These well surface locations fall outside of the prescribed 400' by 400' drilling window centered at the center of each quarter-quarter section, or outside the 800' by 800' drilling window centered at the center of each quarter section and are not located within 50' of an existing well.

The affected surface owner has consented to these locations through an addendum to the lease as recorded 08/27/2010 in Weld county CO, Document #3713734. This document is on file with the state, Document #400113041.

Should you have any questions please contact Clayton Doke at 970-669-7411 or 720-560-2700.

Sincerely,

ROCKY MOUNTAIN PERMITTING, LLC



Terry L. Hoffman  
Permit Agent for HRM Resources, LLC

cc: HRM Resources, LLC  
Andy Peterson